

Gertbot

Rev 2.8, 15 January 2018

The Gertbot is a motor/power controller board for the Raspberry-Pi. The strength of the board is that it has its own CPU which frees up the Raspberry-Pi from a lot of intense computations and will take care of all the real time requirements. All you have to do is give it high level commands. Like: Board 2, Motor 1, take 2432 steps at 67 Hz. Even giving those commands is done for you using the free GUI which comes with it!

Hardware features:

- Four H-bridges 8V-30V, 2.5A.
- Bridges can be re-configured for 2x 5A or 1x 10A.
- Two open drain outputs 30V, 3A.
- Power full 64MHZ ARM Cortex-M3 processor
- RS232 connects direct to the Raspberry-Pi or other serial interface.
- Cascade port to control up to four boards at a time.
- 20-pin connector programmable for:
 - Automatic motor end-stop
 - Four 12-Bit ADC ports
 - Two 12-bit DAC ports
 - 8-16 general purpose I/O
 - Four servo signals

Software controllable features:

- Brushed¹ motors:
 - Control direction
 - Speed control PWM 10Hz-10KHz, 0-100%.
 - Soft start 0.1sec .. 5 seconds prevents in-rush current
 - Stop on switch hit.
 - Full quadrature encoder control.
- Stepper motors:
 - Take X-steps in either direction
 - Step speed 0.06 Hz .. 5KHz.
 - Stop on switch hit.
- Digital Command Control (model train control):
 - Can send any DCC command 3..6 bytes
 - Programmable pre-ambule length and repeat count
- Servo control:
 - Can control up to 4 servos.
 - With speed and trim control.
- Short-circuit or high temperature error detection
- On error, keep running, stop motor, stop board or stop all boards
- I/O pins programmable functions

¹ I used the term 'brushed motor' to indicate the standard DC brushed motors. You find those in most toys.

- Emergency stop, halts whole system.

The board comes with drivers, example code and a GUI all complete with source code. Depending how fast you can screw the wires down, you can have your motors running in a few minutes!

The board can also be used to drive other power electronics like LEDS, relays etc. Using a 30V supply and 2mA LEDS you can drive three sets, each of ~12500 RGB LEDS, using the boards PWM feature to control the colour.

READ THE MANUAL!

The most difficult part of controlling motors has been taken care of by the software running on the Gertbot. Instead of directly having to manipulate the motors, you send high-level commands to the Gertbot which will execute them. But this does mean that you have to learn what those commands are. Therefore you should read the manual.

Quick start:

For those of you who want to start quickly: there is a Gertbot GUI which you can use to control every feature of the Gertbot. There is a separate Gertbot GUI manual which guides you through the controls but it refers to this manual to explain the details of operation.

Advanced:

The Gertbot Advanced guide helps you with cascading boards, operate bridges in parallel to double or quadruple the maximum current. It also tells you how to upload new software versions or how erase the current program and put your own software on the board.

Contents

0	I want to use it NOW!	8
1	Overview:	12
2	Revisions	13
2.1	Revision 2.3	13
2.2	Revision 2.4	13
2.2.1	Linear-stop command Start/stop	13
2.2.2	Stepper motor take steps	13
2.2.3	Filtered end-stops.	13
2.3	Revision 2.5	13
2.3.1	Open collector settings	13
2.3.2	Reverting from DCC mode	14
2.3.3	Support for Quadrature encoders.	14
2.4	Revision 2.6	14
2.4.1	DCC programming.....	14
2.4.2	Quadrature go-to & sync.....	14
2.4.3	Quadrature limits and normal run	14
2.5	Revision 2.7a.....	14
2.6	Revision 2.8	14
3	Software installation & UART control	14
3.1	Pi-3 UART control.....	14
3.2	Stretch image.	15
4	Connecting things up	16
4.1	Connecting Gertbot to a Raspberry-Pi	16
4.2	Connecting motors.	17
4.3	Connecting stepper motors.....	18
4.4	Stepper motors with Connected-middle-tap.....	19
4.5	Connecting motor power.....	19
4.6	Connecting end-stops.....	20
4.7	Connecting Quadrature encoders.	21
4.8	Connecting Open drain output	22
4.9	Connecting to other than Raspberry-Pi	22
4.9.1	Connect to J12 (cascade connector).....	23
4.9.2	Connect to J6 (Pi connector)	24
4.9.3	Connect to J14 (Not mounted)	24
4.10	Connecting servos.	25
5	Enabling the UART.	25
5.1	Pre-Jessie.....	25
5.2	Jessie:	25
5.2.1	Jessie Pi 1, 2a and 2B:.....	25
5.2.2	Jessie / Raspberry-Pi 3:	26
6	Commands.	26
6.1	Identifier.....	26

6.2	Values	27
6.3	Making commands.....	27
6.4	Command table	28
7	Command details	30
7.1	Read version.....	30
7.2	Operation mode.....	30
7.3	End-stop & short/hot set up	32
7.4	Ramp graphs	33
7.5	Corner case ramping behavior	34
7.6	End-stop-2.....	35
7.7	Hot/short	36
7.8	Ramp graphs	36
7.9	Corner case ramping behavior	37
7.10	DC/Brushed Pulse Width Modulation Motor Frequency.....	38
7.11	Brushed Motor Duty Cycle.....	38
7.12	Start/stop Brushed Motor	39
7.13	Read error status	40
7.14	Stepper motor take steps	40
7.15	Stepper Motor Step Frequency	41
7.16	Stepper Motor Ramping.....	42
7.17	Stop all	42
7.18	Switch open drain	43
7.19	Set DAC.....	43
7.20	Read ADC.....	43
7.21	Read I/O	43
7.22	Write I/O	44
7.23	Set I/O	44
7.24	Set ADC/DAC	45
7.25	Board configure	46
7.25.1	Board Synchronous command mode.	46
7.25.2	'Attention' signal mode.....	46
7.25.3	Channel error mode.....	46
7.26	Ramp graphs	47
7.27	Corner case ramping behavior	47
7.27.1	Board configure command overview	48
7.28	Read board status	48
7.29	Ramp graphs	50
7.30	Corner case ramping behavior	50
7.31	Read motor status.....	51
7.32	Sync.....	51
7.33	Poll	52
7.34	Power off / Emergency halt	52
7.35	Read back I/O configuration	52
7.36	Send DCC message.....	52
7.37	DCC configuration.....	52
7.38	Read back Motor configuration	52

7.39	Read back Motor Missed steps	53
7.40	Set Ramp rate.....	53
7.41	Set baud rate.....	53
7.42	Enable/disable quadrature encoder	54
7.43	Read quadrature encoder.....	54
7.44	quadrature encoder goto.....	54
7.45	Quadrature control	54
8	Digital Command Control.....	55
8.1	DCC command.....	56
8.2	DCC configure	56
8.3	Connecting it up.....	58
9	Quadrature encoder.....	59
9.1	Maximum operating frequency.....	59
9.2	Position & direction	59
9.3	Operation.....	59
9.4	Limits.....	59
9.5	Overshoot, go-slow.....	60
9.6	Ramp-up settings.....	60
10	Servo mode	61
10.1	Signal	61
10.2	Speed.....	61
10.3	Ramping.....	62
10.4	Commands	62
11	Operating details	64
11.1	End-stops.....	64
11.2	Halt.....	65
11.3	Frequency settings	66
11.3.1	Jitter.....	66
11.3.2	Accuracy.....	66
11.4	Synchronous operation.....	67
11.4.1	Direct commands.....	67
11.4.2	Synchronous commands	68
12	Stepper motor ramping.....	69
12.1	Ramp parameters	69
12.2	Ramp behavior	70
12.3	Ramp graphs	71
12.4	Corner case ramping behavior	71
13	Motor error.....	72
13.1	Reaction to an error.....	72
13.2	Oscillation.....	73
13.3	Brushed motor start/stop.....	73
14	Appendix A: error codes.....	75
15	Software.....	77

15.1	Gertbot Gui.	77
15.2	Gertbot C-drivers.	77
15.3	Gertbot Python-drivers.....	77
15.4	Gertbot DCC GUI.	77
16	Appendix B: Technology.	78
16.1	DC voltage.	78
16.2	AC voltage.	78
16.3	H-bridge.	79
16.4	DC Brushed motor.	80
16.5	Stepper motor.....	81
16.5.1	Connections.....	81
16.5.2	Mechanics	82
16.5.3	Rotor hold.	82
16.6	Inductors.	83
16.6.1	Switching it on.	83
16.6.2	Switching it off.....	84
16.7	Quadrature encoders.	84

Revision 2.8, January-2018.

New:

Servo control.

Release 2.8 has the code which allows servos to be controlled alongside DC or stepper motors.


Stepper motor ramping.

Release 2.8 has the code which allows stepper motors to gradually reach their maximum speed.

0 I want to use it NOW!


If you are like a lot of engineers you don't want to read a manual, you want to get started NOW. I can't recommend that but this chapter might limit the damage if you still want to do so. Please use the following steps:

1. Connect a DC-brushed motor or stepper motor to the Gertbot. Also connect a power supply for your motors to the Gertbot. See *Error! Reference source not found. Error! Reference source not found.* w to do that.
(From here the instructions assumes you have connected a DC motor to contacts A1,A2 or a stepper motor to contacts A1,A2,B1,B2)
2. Plug the Gertbot board on top of a Raspberry-Pi board which is powered down. Then boot the device.
(On a B+ make sure to plug the board on GPIO pins 1-26.)
3. Login and download the software: `git clone git://github.com/<TODO>`
(You might want to make a directory to put all the Gertbot data into)
4. If you have not started the X-windows system yet, do so now: `startx`
5. Open a terminal window and go to the directory where you have cloned the Gertbot GUI software.
Type `./gertbot` (That is dot-slash-gertbot). (You may get a warning that your UART is not available. If so follow the instructions to enable the UART.) After that you see this:




(The "Com.." is only present if you run the gui under windows)

6. Press the **Connect** button. A log window will pop-up and show the search for boards. Default from the factory the board has ID 3 so you should see this:




On the right hand side is the log windows which we will ignore for now.

7. Use the control under “**Motor 0**” to select the operating mode. There are 6 modes but for now select **DC/brushed** for a DC or brushed motor
Step Gray Off for a stepper motor




8. For DC/brushed motors you see this:





You can now play with the  buttons and your motor should run.

If you have a big motor the over-current protection might kick in. (This can be so fast so you will not notice it. All you find is that your motor does not start). If so press the “More” button and set the Ramp-Up speed to 1 second (See §13.3 *Brushed motor start/stop* for details about that)



9. For stepper motors you see this:



You can now play with the  buttons and your motor should take 10 steps. You can change the 'Frequency' and 'Steps' values on the screen to see what they do.


Your stepper motor will have a maximum frequency above which it does not work reliable anymore. If your stepper motor is 'rattling' or only moves back-and-forth you have either connected the wires wrong or one of your connections is failing.

For more information about the Gui read the manual: Gertbot-Gui document.

1 Overview:

The boards consist of:

- A Central Processing Unit (CPU)
- Four H-bridges each 2.5A
- Two open drain outputs
- Two Digital-to-Analog converters (in CPU)
- Four Analog-to-Digital converters (in CPU)
- 10 general purpose input/output ports
- A UART connection
- A cascade port



The four H-bridges can be used to control either four brushed motors or two stepper motors or two brushed and one stepper motor. You talk to the board using the UART (serial port) which must be set to 57600 baud, 8 bits 1 start, 1 stop bit, no parity.

The Gertbot is controlled by sending commands over the UART port. There are commands to select what type of motors you have (brushed or stepper or a mixture). There are commands to run your motors, to specify when they should stop, to control the relays, read the ADC, set the DAC and a lot more.

There is an expansion connector which allows you to connect up to four Gertbot boards in parallel. This gives you control over maximum 8 stepper motors or 16 brushed motors or various mixtures of both.

The board has four LEDs labeled as D5, D6, D7 and D8. At the moment only three of those are used:

- D8: Heartbeat. Slowly blinking. Indicates the main system loop is running.
- D7: Error. Fast blinking. Indicates there are errors in the error queue. Reading the errors from the queue (using the read error command) will stop the blinking.
- D6: Halt. Steady on. Indicates the HALT line is active.
- D5: Currently unused.

The general purpose I/O ports can be used for various features: end-stop input, quadrature encoder input and some can be used as ADC or DAC. When not used for any of these functions the user can read or write the pins.

2 Revisions

2.1 Revision 2.3

First official released revision.

2.2 Revision 2.4

Released February 2015. This manual has also been updated with Rev 2.3 commands which I forgot to document.

2.2.1 Linear-stop command Start/stop

Brushed Motor (0xA0 0x06 <id> <mode> 0x50)

The 'stop' version of this command is supposed to also stop stepper motors. This was not working in release 2.3. Fixed in release 2.4.

2.2.2 Stepper motor take steps

(0xA0 0x08 <id> <MS ><MM><LS> 0x50)

The channel-2 stepper motor was taking the first step in the previous direction.

Thus a command

<left 4 steps>

followed by

<right 4 steps>

Would execute as :

step left 4 times

followed by

step left 1 time

step right 3 times

Fixed in release 2.4.

2.2.3 Filtered end-stops.

For brushed mode, the end-stops were implemented in an interrupt service routine making them extremely fast. Practice has shown that the end-stop signals were likely to have glitches on them especially with long wires and noisy motors. Therefore the revision 2.4 now supports end-stop glitch filtering. The filtering is done using an integrator with a 1-millisecond sampler. The user can set an integrator limit between 1 and 255.

2.3 Revision 2.5

Released 14 April 2015.

2.3.1 Open collector settings

When setting the output levels, the open collector pins would revert to input mode. The fix in 2.4 was not working. This is now fixed.

2.3.2 Reverting from DCC mode

When switching to Brushed mode from DCC mode the PWM of the brushed motors would no longer work. This is now fixed.

2.3.3 Support for Quadrature encoders.

The support for quadrature encoders is the biggest change to the rev 2.5 software. For details read § 9 *Quadrature encoder*.

2.4 Revision 2.6

Released 26 April 2015.

2.4.1 DCC programming.

In DCC mode it was not possible to program some DCC controllers. This was due to the fact that there were idle packets between the commands. Even when setting the ‘no idles’ control bit there would still be at least one idle packet. In revision 2.6 idle packets are complete suppressed *when the ‘no idles’ control bit is set*. Also there is now at least a 20ms gap after a reset packet.

2.4.2 Quadrature go-to & sync

The “sync” feature also works with quadrature “go-to” commands.

2.4.3 Quadrature limits and normal run

Previously a normal “Start Brushed motor” command would start the motor even if the position was beyond the quadrature limits. The motor would be stopped soon but that takes a short time. Thus each time the “Start Brushed motor” is given the motor will move a bit further past the set limits.

Now if a motor is at or past the quadrature limits, a “Start Brushed motor” command will be ignored.

2.5 Revision 2.7a

Alpha release 14 June 2015.

The 2.7 release has support for controlling servo motors. A maximum of four servo motors can be controlled.

This is an early alpha release which has not been fully tested.

2.6 Revision 2.8

The 2.8 release has support for ramping up and down the speed of stepper motors.

3 Software installation & UART control

Since the very first release a four year ago a number of changes to the raspberry-Pi hardware and software have occurred. Unfortunately this means the Gertbot no longer work ‘out of the box’. At the moment developments are ongoing to make this happen again but in the meantime this chapter helps you getting the Gertbot running.

3.1 Pi-3 UART control.

With the introduction of the Raspberry-Pi 3 the mini UART has been re-allocated to drive the Bluetooth device.

To enable the mini UART for the Gertbot the following changes must be made to the system:

Add to the /boot/config.txt file:

- dtoverlay=pi3-disable-bt
- enable_uart=1

Remove from the /boot/cmdline.txt file

- console=serial0,115200 console=tty1

For both you need a text editor and use the 'sudo' command e.g.

```
sudo nano /boot/config.txt.
```


```
sudo nano /boot/ cmdline.txt.
```

Or for the older generation:

```
sudo vi /boot/config.txt.
```

```
sudo vi /boot/ cmdline.txt.
```

Don't touch the serial settings in the Raspberry-Pi interface configuration:



3.2 Stretch image.

The old Rasbian images (The latest of that is the Jessie image) work with the Gertbot GUI program without requiring any extra actions from the user.


The newest Rasbian image (called Stretch) no longer has support for the old Qt4 libraries. To use the old Gertbot programs you have to install the libraries manually. If you try to run an old program under stretch you get the error message:

libQtGui.so.4: cannot open shared object file: No such file or directory

To fix the problem open a command prompt and type:

```
sudo apt-get install libqtgui4
```

A command window appears if you click on the command icon in the taskbar:



At the moment work is in progress to add the Gertbot executable to the standard Debian software pool. When that is finished you can just use 'apt-get install' to get the right software version plus the libraries.

4 Connecting things up

4.1 Connecting Gertbot to a Raspberry-Pi

You plug the board on top of a raspberry-Pi. If you want to connect more than one board (cascade) please see the chapter in the 'Gertbot advanced guide'.

Rev A or B:

The board has 26 pins as has the Gertbot:



Raspberry-Pi B with Gertbot.

Revision B+, Rev2 or Rev 3: The board goes on the outside 26 pins:




Raspberry-Pi B+ with Gertbot.

You will find that if you do not plug it in the right way. e.g. misalign by one pin , the board will bump against the Ethernet connector.

4.2 Connecting motors.


The contacts for the motors are identified on the board using the notion A1, A2, B1, B2, C1, C2, D1, D2. A motor coil is always connected between X1 and X2. Thus between A1 and A2, B1 and B2 etc.

Looking at the top of the board you get these connections:




Gertbot Top view.

In order to connect motors and power supplies use the following diagram:




Gertbot **Top view. DC/brushed motors**



Gertbot **Top view. Stepper motors**

Notice that there is only one ground (blue) but the top outputs (A/B) and the bottom outputs (C/D) *can* have a different power supply. But if you need only one supply you can connect it to both VAB and VCD at the same time.

If you ever forget and don't have this manual available: At the **bottom of the board** you find a diagram which shows where to connect the motor coils and the power supplies.



Gertbot **BOTTOM VIEW.**

4.3 Connecting stepper motors.

Brushed motors have a high impedance and you can connect a brushed motor direct to the board. This is not the case with a lot of stepper motors!


Beware!
Some stepper motors may need series resistors to connect them to the board.

The controller needs a minimum of 8V to work. If your stepper motor requires less voltage you must add series resistor.

If you connect up a stepper motor you will need to use a pair of connections. Thus a stepper motor connects to A1 & A2 and B1 & B2. Most likely your stepper motors has four or six wires. For details about stepper motors see chapter *16.5 Stepper motor*.

4.4 Stepper motors with Connected-middle-tap.

There are stepper motors which have a middle tap and the middle taps of both coils are connected. A know series is the 24BYJ28 series:



This type of configuration is intended to be used with four open-collector drivers. (See the second picture of paragraph 16.5.1). It is possible to drive these motors from the Gertbot. You connect the common wire to ground and the other wires connect as usual to the four outputs as with a normal stepper motor.

The Gertbot output are set up to *drive* current, not *sink* current. Therefore, in contrast to the image in paragraph 16.5.1, the middle tap is not connected to power but to *ground*.

Just like me, you might happen to get one of those motors where the wiring colour does *not* correspond to the data on the internet. To find out which wires pair up is a bit of a challenge. I solved it as follows: Use an ohm meter to find which wires is the common one. Next apply power to the common wire and one arbitrary wire. You will find you can no longer turn the axle as the magnetic field keeps the axel locked. Then select one of the remaining wires and apply power to it as well. If you can turn the axel that set of wires pair up (as the magnetic fields cancel each other out). If not, try it with the next wire.

4.5 Connecting motor power

For a motor to run you must connect an external power supply. The motor controllers should be connected to a power source between 8 and 18Volt.

**For safe operation do not
 connect more than 18volts!!**

The board can withstand operating voltages up to 30V but anything above 18V can cause dangerous voltage levels to appear on the motor output pins.

The bridge controllers need a minimum of 8V. If the input voltage is below 8V the controller will refuse to work. The power is connect with the plus connected to pin VAB or VCD. The ground goes to the Gnd connections. You can use a different voltage for VAB as for VCD, but all grounds of the board are connected together.


Again at the bottom of the board you find a diagram which shows the power connections connected to a battery symbol.

If you have a motor for a voltage less than 8volts you can try to connect it using a series power resistor. This will work for stepper as well as brushed motors.

4.6 Connecting end-stops.

To connect end-stops you have to add a contact between one of the EXT pins and ground. You can use a mechanical switch or an optical switch. As each EXT pins has a pull-up resistor of 4700 Ohms to the controller's 3.3 volt supply you only need to connect a switch between the pin and ground.

These are the J3 pins which can be programmed as end-stop:




Gertbot end-stop pins.

Looking at the pins above the end-stops are assigned as follows:

Motor 3:B	Motor 2:B	Motor 1:B	Motor 0:B
Motor 3:A	Motor 2:A	Motor 1:A	Motor 0:A

As stated all you need is a switch from the pin to ground. The following diagram shows how to connect all four B end-stop switches:



You can connect a switch which is normally open and gets closed if the end-stop position is reached. In that case you must program the end-stop as active low.

Alternative you can connect a switch which is normally closed and gets opened if the end-stop position is reached. In that case you must program the end-stop as active high. This is the preferred way of connecting an end-stop.

If you use end-stops you **MUST** make sure your motor's rotational direction is correct. The simplest way is to use the GUI and use the button of the GUI to make the motor move into the direction of end-stop A. If the motor goes into the opposite direction swap your motor wires around or swap your end-stop wires around. Also test your end-stop. There are two ways to do this:


1. Set the motor moving, operate the end-stop e.g. with a finger and check that the motor stops.
2. Operate the end-stop and check that the motor refuses to start in that direction

Recently I had an application where the motors would stop often without apparent reason. I found that this was caused by induction spikes into the end-stop wires. Initially I tried adding 300 Ohm pull-up resistors but that did not help much. I solved this by adding capacitors between the input and ground. I had to go up to 4.7uF before the noise was suppressed. I am working on a low-pass filter in software on those inputs.

4.7 Connecting Quadrature encoders.

To use a quadrature encoder you must connect them to the end-stop pins. Thus you can use either end-stops or a quadrature encoder, but not both.

These are the J3 pins which can be used as quadrature encoder:



Gertbot quadrature encoder pins.

Looking at the pins above the quadrature encoder are assigned as follows:


Motor 3:I	Motor 2:I	Motor 1:I	Motor 0:I
Motor 3:II	Motor 2:II	Motor 1:II	Motor 0:II

If you find that the encoder value is “the wrong way around”.
(You expected it to increment, but it decrements) you can:

- swap the terminal I and II around
- or
- There is a SW option to invert to operation of the counter.

4.8 Connecting Open drain output

The Gertbot has two open drain ports. The switch element is an NMOSFET. Each can switch 30V 3A. The following picture shows the open drain connections:



Gertbot open drain connections.

For those who are not familiar with open drain connections: An open drain is like a switch. But you can only switch DC currents and you must connect the plus to the drain pin (OD0 or OD1).



As you can see from the diagram above, there is no power available at the output. For an open drain output to work, the user must provide an external power source. The open drain output does nothing more than provide a path with a very low resistance to ground when it is switched on.

There is no protection on the open drain outputs. So the board will get damaged if you exceed the current or voltage specification. MOSFETS have the notorious habit of a large capacitive coupling from the drain to the gate. To prevent capacitive voltage spikes from blowing up the controller there is RC filtering between the gate and the controller. However there is no guarantee that it will protect under all circumstances.

4.9 Connecting to other than Raspberry-Pi

The Gertbot takes commands from a standard UART stream. (UART stands for Universal Aynchronous Receive Transmit). Thus you can control the boards from any equipment which has a UART port. This can be an Arduino or a windows PC.

Beware of the difference between a UART stream and a RS232 stream. The UART stream is a protocol. RS232 is a physical interface standard. ***Do not connect the board to an RS232 port. RS232 has a voltage swing between +/- 3V and +/- 15Volts. It will damage the board.***

The requirements for a serial port are:

- Amplitude 3.3 Volts
- 57600 baud
- 8 data bits
- 1 start bit
- 1 stop bit
- No parity

Thus any equipment which can read and write a serial UART stream can be used to control the boards. The board does not use flow control.

Other than plugging the Gertbot to the top of a Raspberry-Pi here are three ways to connect a serial device:



4.9.1 Connect to J12 (cascade connector)

This is the easiest way but prevents you from using more than one board. You will need an 8 pin female header organised as two rows of 4 pins 0.1" pin pitch. Connect the signals as follows:

Signal	Pin	Pin type on Gertbot
Ground	1	Ground
5Volt ~65mA	3	Power
Transmit	6	Input
Receive	4	Output
Attention (Optional)	5	Output

Transmit is the transmit pin of your external computer. It is a receive pin of the Gertbot. Receive is the receive pin of your external computer. It is a transmit pin of the Gertbot.

Below is a picture of a FTDI USB to TTL cable connected to J12. The 5V output of the cable can power the Gertbot so no external 5V supply is required.



Rx is the external computer receive, it is the Gertbot transmit.
Tx is the external computer transmit, it is the Gertbot receive.

4.9.2 Connect to J6 (Pi connector)

You will need minimal a 10 pin male header organised as two rows of 5 pins 0.1" pin pitch. (Maximum you can use a 26 pin male header organised as two rows of 13 pins 0.1" pin pitch) Connect the signals as follows:

Signal	Pin	Pin type on Gertbot
Ground	6	Ground
5Volt ~65mA	2 and/or 4	Power
Transmit	8	Input
Receive	10	Output
Attention (Optional)	22	Output

Transmit is the transmit pin of your external computer. It is a receive pin of the Gertbot.
Receive is the receive pin of your external computer. It is a transmit pin of the Gertbot.

(Not picture is available of this)


4.9.3 Connect to J14 (Not mounted)

For this you will need to solder a connector on the Gertbot. You will need a 5 pin male header organised as one row of 5 pins 0.1" pin pitch. Connect the signals as follows:

Signal	Pin	Pin type on Gertbot
5Volt ~65mA	1	Power
Ground	2	Ground
Transmit	3	Input
Receive	4	Output
Attention (Optional)	5	Output

Transmit is the transmit pin of your external computer. It is a receive pin of the Gertbot.
Receive is the receive pin of your external computer. It is a transmit pin of the Gertbot.


Below is a picture of a FTDI USB to TTL cable connected to J14. The 5V output of the FTDI cable can power the Gertbot so no external 5V supply is required.



4.10 Connecting servos.

The control signals for the servo motors come from P3.

- SERVO 0 : P3 pin 14
- SERVO 1 : P3 pin 2
- SERVO 2 : P3 pin 1
- SERVO 3 : P3 pin 18



5 Enabling the UART.

The gertbot takes its command from the Raspberry-Pi Auxiliary UART port. This port is not enabled by default on a new Raspberry-Pi image. I wrote a program 'enable_uart' which takes care of the difficult parts but the constant flow of new hardware and new operating systems makes that unreliable.

5.1 Pre-Jessie

The enable_uart program which can be downloaded from here https://www.gertbot.com/gbdownload/pi/enable_uart_exe.tgz will do the job.

Just start the program with NO arguments and it will give you instructions.

Then PLEASE READ THE INSTRUCTION and follow them.

5.2 Jessie:

5.2.1 Jessie Pi 1, 2a and 2B:

In jessie there is a rasp-config program. Click the 'enable UART' button.

5.2.2 Jessie / Raspberry-Pi 3:

On the Raspberry-Pi 3 the auxilliary (or mini) UART port has been used to control the Wi-Fi and Bluetooth devices. As a result all add-on cards which use the UART no longer work. For example xbee and other transmitters, RS485 and unfortunately also the gertbot. There are several threads about this:

- Overlay to remap Pi 3 UART
<https://www.raspberrypi.org/forums/viewtopic.php?f=107&t=138223&hilit=dtoverlay+miniuart&start=100#p917501>
- Serial issues
<https://www.raspberrypi.org/forums/viewtopic.php?f=63&t=151454&p=1034870&hilit=dtoverlay+miniuart#p993505>

Solution

I found that the following worked for me:

- Add "dtoverlay=pi3-miniuart-bt" to the /boot/config.txt file.
- Also add "enable_uart=1" to that /boot/config.txt file
- Remove "console=serial0,115200 console=tty1" from the /boot/cmdline.txt file

As this swaps the mini UART back to pins 14 & 15 on the GPIO connector, the WiFi and Bluetooth functionality is lost. Thus it is not possible to use gertbot and Wifi And Bluetooth at the same time.

I have heard that some people managed to use the software (bit-bang) UART emulator on pins 14 & 15 alongside WiFi and Bluetooth. Thus far I have not been able to get this working with the Gertbot. Probably because (Just as with e.g. xbee) the data is a packet oriented stream with no buffering and binary data.

6 Commands.

All commands are 8 bit bytes and are in **binary** format, *not ASCII*, so you cannot type these values into a terminal program. Each command must be preceded by the value 0xA0 and closed with the value 0x50. Alternative you can make a file with commands and then send that file to the UART port e.g.:

```
cp start_all_engines.bin /dev/ttyAMA0
```

The Gertbot comes with several support programs one of which is a GUI which lets you control your Gertbot boards using only your mouse and allows you to make commands files as mentioned above.

6.1 Identifier

You can control multiple boards each with up to four motors. Therefore most commands have an identifier (ID) byte which tells for which board and for which motor on that board the command is intended. As you can cascade a maximum of four boards each with maximum four motors that gives you 4x4=16 potential motors to control. Therefore the ID byte can range from 0 to 15. The ID's 0-3 are for the first board, 4-7 for the second etc. The H-bridge outputs are identified on the board using the notion A1, A2, B1, B2, C1, C2, D1, D2. See § *Error! Reference source not found. Error! Reference source not*

und. on how to connect your motor to those. The following table specifies the relation between the ID and the connections (motors) it controls.

ID	Board	Connections	ID	Board	Connections
0	0	A1-A2	8	2	A1-A2
1	0	B1-B2	9	2	B1-B2
2	0	C1-C2	10	2	C1-C2
3	0	D1-D2	11	2	D1-D2
4	1	A1-A2	12	3	A1-A2
5	1	B1-B2	13	3	B1-B2
6	1	C1-C2	14	3	C1-C2
7	1	D1-D2	15	3	D1-D2

If you are operating stepper motors you need two pair of connections for one stepper motor. Thus the four connections A1, A2, B1 and B2 together control *one* stepper motor. The same holds for the set of C1, C2, D1 and D2 which together control *another* stepper motor. As all of those **MUST** work in unison, a stepper motor id can only be even: 0,2,4,6,8,10,12. Thus sending a command to id 0 will control all four of the outputs A1, A2, B1, B2. Stepper motor commands send to an odd ID will be ignored and raise an error.

Some commands are not designated for a motor but for the board itself. In that case the ID value 0,1,2,3 are all treated as for the first board, ID values 4-7 address second board etc.

6.2 Values

Many commands take one or more parameters. As mentioned before all data is send in binary format. Thus a value of 76 (decimal) is send as 0x4C (0x mean the number is in hexadecimal format). Sometimes values are too big to fit in a single byte and instead two or three bytes must be used. In all cases the most significant (MS) value is in the first byte. Thus the least significant (LS) value is in the last byte. This is the case for transmitted as well as received data. For example to send the value 27616 you have to first translate this to hex: 0x6BE0 and then send it as two bytes: 0x6B followed by the byte 0xE0. If you have to send a big number e.g. 4705118 you send three bytes: 0x47 0xCB 0x5E. There is one command which takes signed number: the step command. In that case you must make sure your three bytes are accordingly signed (twos complement format²). See also the examples here: § 7.14 *Stepper motor take steps*.

6.3 Making commands

The commands seem complex and making an error in them is easily done. The Gertbot Gui is an alternative of making commands with little effort. So easy that these days I rarely refer to the command manual. Instead I give the command using the Gui and then copy the hex values from the log window in my program. (But I still needed the text below to put the correct code in the Gui).

² Explanation of twos complement is outside the scope of this manual. Please read up on that.

6.4 Command table

Command	Val		Parameters
Operation mode	0x01	id	0:off,1:brushed, servo, stepper etc.
End-stop & hot/short ³	0x02	id	1 byte
Board status	0x03	ID	Return status of board
DC motor Frequency	0x04	id	2 byte value. Range 10-30K
DC motor duty Cycle	0x05	id	2 byte value. Range 0-1024 for 0-100%
Start brushed motor	0x06	id	0: Stop, 1: Move A, 2: Move B
Read error status	0x07	ID	Returns 0x07, id, 2 byte error code
Stepper motor take steps	0x08	id	3 byte signed value. 0 stops.
Step Freq.	0x09	id	3 byte value. Range 16-128000
Stop all	0x0A	0x81	Stops all motors on all boards
Open Drain	0x0B	id ¹	0:idle, 1:active,
Set DAC	0x0C	id ¹	2 byte value
Read ADC	0x0D	id	Returns 0x0D,id, 2 byte error code
Read I/O	0x0E	ID	3 bytes
Write I/O	0x0F	ID	3 bytes
Set I/O	0x10	ID	3 bytes
Set ADC/DAC	0x11	ID	ADC byte DAC byte
Configure	0x12	ID	3 bytes
Read board version	0x13	ID	Returns 0x13,id, 2 byte version
Motor status	0x14	ID	Return 16 status bytes
Execute Sync.	0x15	0x18	Execute all synchronised commands
Poll error status	0x16	id	return error status of board
Power off/emergency stop	0x17	0x81	Power down all motors on all board
Read I/O configuration	0x18	id	Returns I/O settings
DCC message	0x19	CID	6 bytes
DCC configuration	0x1A	ID	4 bytes
Read motor configuration	0x1B	ID	Returns 16 bytes
Read motor missed steps	0x1C	ID	Returns 8 bytes
Set ramp rates	0x1D	ID	{down,up},halt
End stop-2	0x1F	ID	3 bytes, up, down, halt
<Reserved>	0x20	-	-
Hot/Short	0x21	ID	1 byte MS 4 bits!
Set Baud rate	0x22	0x18	0x81 <baudrate 0..4>
quadrature encoder on/off	0x23	id	flags, position (3 bytes)
quadrature read	0x24	id	returns position
quadrature encoder go to	0x25	id	position (3 bytes)
quad. encoder control	0x26	id	flags(1), Max (3), Min (3), Dist. (2)
servo config	0x27	id	speed(2) ramp, OC, trim min(2), max(2)
servo set	0x28	id	Value MS, Value LS

For more information see the next chapter: *Command details*.

id¹: id can be 0,1,4,5,8,9,12,13 only.

ID: Board id, least significant two id bits are ignored.

³ Superseded by new command since rev 2.4

CID: Channel ID mask. See DCC section of this manual.

7 Command details

This chapter lists each command, the command format the parameters and often examples.

Each command that generates a response from the Gertbot (The Gertbot send back a number of reply bytes) has to send multiple closing bytes (Value 0x50). To be precise, if a command returns X bytes the command must be followed by X times the 0x50 value.

Throughout this document you will find references to 'Direction A' or 'Direction B'. I use the terms A and B as the real physical direction depends on how the motor wires are connected. e.g. for a brushed motor the direction inverts when the two wires are swapped.

7.1 Read version

0xA0 0x13 <ID> 0x50 0x50 0x50 0x50

This command returns the version of the board indicated with ID.

ID can be in the range 0-15 but the LS two bits are ignored.

This command will return 4 bytes.

The first byte is the original ID.

The second is 0x13

Bytes three and four are the MS & LS values of the version code.

As the command returns 4 bytes it must be followed by at least 4 bytes of 0x50.

7.2 Operation mode

0xA0 0x01 <id> <mode> 0x50

This command sets the operation mode of a motor. The id can be in the range 0-15 for brushed motors.

The id must be even for stepper motors. If you set a motor up as stepper motor, the following motor (with id+1) is disabled. Thus if you set motor 0 to stepper mode you can no longer send commands to motor 1. You can NOT set motor 1 to stepper mode.

These are the currently operating modes:

0: Switch motor <id> off

1: Motor <id> is operating in brushed mode

2: Motor <id> is operating in DCC⁴ mode

3: Motor <id> is operating in Servo mode

8: Motor <id> is setup as stepper motor using Gray code. The <id+1> is no longer usable.

9: Motor <id> is setup as stepper motor using Pulse code. The <id+1> is no longer usable.

All other values are illegal.

⁴ DCC stands for Digital Command Control. A method of controlling model railway objects.

Stepper power.

If operating in stepper mode there is an extra –power on/off bit: bit 4. If that is set the stepper motors keep power on their stator when stopper. If that bit is clear the stepper motors are powered down when finished stepping. In effect this give the following operating modes:

- 0x00: Switch motor <id> off
- 0x01: Motor <id> is operating in brushed mode
- [0x02: Motor <id> is operating in DCC mode] (Under development)
- 0x08: Motor <id> is setup as stepper motor using Gray code. The <id+1> is no longer usable.
The motor will power off when done.
- 0x09: Motor <id> is setup as stepper motor using Pulse code. The <id+1> is no longer usable.
The motor will power off when done.
- 0x18: Motor <id> is setup as stepper motor using Gray code. The <id+1> is no longer usable.
The motor will power off when done.
- 0x19: Motor <id> is setup as stepper motor using Pulse code. The <id+1> is no longer usable.
The motor will power off when done.

All other values are illegal.

If a motor pair is set up as stepper motors all command for the pair must go to the lowest id. There are two stepper motor modes, each has a different waveform.

After sending a mode to a motor you must specify a frequency before the motor can be used, (even if the motor was already in that same mode.)

Mode 8.

Stepper motor mode 1 uses gray coded outputs:




Figure a: Mode 1, gray waveform: positive steps.




Figure b: Mode 1, gray waveform: negative steps.

Mode 9.

Stepper motor mode 2 uses pulse coded outputs:




Figure c: Mode 2, pulse waveform: positive steps.




Figure d: Mode 2, pulse waveform: negative steps.

7.3 End-stop & short/hot set up

0xA0 0x02 <id> <end-stop & short/hot mode> 0x50

<This command is still available but is superseded in revision 2.4>

This command enables or disables the end-stop mode of a motor and sets the end-stop polarity. It also sets the motor short/hot response.

Endstop.

Bits 0,1 enable/disable each of the two end-stops. Bits 2,3 set the end-stop polarity. For more details about end-stops see chapter 9 .

Bits 1,0	End-stop mode
0	Both off
1	A is on B is off
2	A is off B is on
3	A and B are on

End-stop enable bits

Bits 3,2	End-stop mode
0	Both active low
1	A active high B is active low
2	A active low B is active high
3	Both active high

End-stop polarity bits

- Active high mean the motor is stopped if the end-stop input is high.
- Active low mean the motor is stopped if the end-stop input is low.

The enable and polarity bits are send combined in the LS 4 bits of the command. The MS bits are reserved for future use.

Short/Hot response.

Each motor controller has 2 error signals. When an error is detected the channel is disabled to prevent damaging the output. The error signal is also passed to the microcontroller which can respond to it. For more details see § 0 **Ramp down:**

Ramp-down begins when there are a limited number of steps still to take. The Gertbot software calculates the exact position (number of remaining steps still to take) where this process is started.

1. Each **step** the frequency decrements with the rate of change
2. Once the start/stop frequency has been reached it stays at the frequency.

At that moment the ramp-down has finished. That will coincides with the moment that there are no more steps to take.


The algorithm has some safeguards:

- It will not step faster than the specified operating frequency
- It will not step slower than the specified start/stop frequency


If there are not enough steps to take, the stepper motor might not get to the operating frequency. An extreme example would be where the user specifies only a single step. That step will then only be taken with the start/stop frequency.

7.4 Ramp graphs

Because the step frequency changes **per step** the frequency does not go up or down linearly. Here is a typical graph of the step frequency (Vertical) against time (Horizontal).



If there are not enough steps to reach the operating frequency the Gertbot starts ramping down early. This is required otherwise the motor will not be able to stop with the specified minimum step rate. The following is the graph of such a step sequence:



7.5 Corner case ramping behavior

When using ramping there are a number of operating cases the user has to be aware of:

- On a 'stop' command (normal, emergency or end-stop) the stepper motor is stopped right then and there. No ramping down takes place!
- No new step command should be giving whilst a previous one is still in operation. If so the stepping process starts immediately with the (slow) start frequency.
- When running at the operating frequency a new frequency command will take effect immediately. Thus no ramping up (if the new frequency is higher) or ramping down (if the new frequency is lower) to the new frequency will take place.

Motor error.

The user can program the following responses:

- Ignore error: The controller takes no further action.
- Stop channel: Stop the channel with the error.
(This is not available for stepper motors)
- Stop channel pair: Stop both channels of the motor controller.
- Stop board: Stop all motor controllers of the board (four channels).
- Stop system: Stop all motors on all boards.

Code	Error handling
0000	No error propagation
0001	Stop channels A,B,C,D
0010	Stop channel pair A&B (C&D)
0011	Stop board (A-D)
0100	Stop system (A-D on all boards)
<others>	<Unused>

The error handling bits are placed in bits 4-7 of the byte.

Example : On board 0 motor 2, set both end-stops active low, error mode is Stop channel: 0xA0 0x02 0x02 0x13 0x50.

End stops are very useful to implement basic motor control. e.g. to open a garage door you would activate an end-stop switch when the door is full opened and a second switch when it is fully closed. Next you only have to send the command to start the motor in a certain direction. You do not have to send a stop command at the right time as the Gertbot itself will stop the motor when the end-stop switch is activated.

7.6 End-stop-2

0xA0 0x1F <id> <end-stop> <time A> <time B> 0x50

From software version 2.4 onwards there is a new end-stop command: end-stop 2. This new command allows to user to set a 'low-pass filter'. The filter is implemented using an 'integrator' function. The end-stop signal is sampled every millisecond and a counter keeps track if the signal is active (the counter is incremented) or inactive (the counter is decremented). The end-stop is seen as 'triggered' if the counter reaches a certain threshold. The user can set threshold between 0 (filtering disabled) or 255 (signal must be active for 255 milliseconds). A filter value of 0 means the Gertbot uses the interrupt routine to stop the motor. This is compatible with SW versions before 2.4.

The end-stop 2 command uses the same 4 LS bits of the first byte to indicate on/off and polarity:

Bits 0,1 enable/disable each of the two end-stops. Bits 2,3 set the end-stop polarity. For more details

Bits 1,0	End-stop mode
0	Both off
1	A is on B is off
2	A is off B is on
3	A and B are on

End-stop enable bits

Bits 3,2	End-stop mode
0	Both active low
1	A active high B is active low
2	A active low B is active high
3	Both active high

End-stop polarity bits

- Active high mean the motor is stopped if the end-stop input is high.
- Active low mean the motor is stopped if the end-stop input is low.

The enable and polarity bits are send combined in the LS 4 bits of the command. The MS bits are reserved for future use.

New is that the command is followed by two time-value each in the range 0-255. The first one is for channel A the second is for channel B.

The new end-stop command has no setting for the hot/short mode anymore. A new separate hot/short command has been added.

7.7 Hot/short

The new command has the same code as the old end-stop AND hot short/command, but the LS 4 bits are ignored:

Short/Hot response.

Each motor controller has 2 error signals. When an error is detected the channel is disabled to prevent damaging the output. The error signal is also passed to the microcontroller which can respond to it. For more details see § 0 *Ramp down*:

Ramp-down begins when there are a limited number of steps still to take. The Gertbot software calculates the exact position (number of remaining steps still to take) where this process is started.

3. Each *step* the frequency decrements with the rate of change
4. Once the start/stop frequency has been reached it stays at the frequency.

At that moment the ramp-down has finished. That will coincide with the moment that there are no more steps to take.


The algorithm has some safeguards:

- It will not step faster than the specified operating frequency
- It will not step slower than the specified start/stop frequency


If there are not enough steps to take, the stepper motor might not get to the operating frequency. An extreme example would be where the user specifies only a single step. That step will then only be taken with the start/stop frequency.

7.8 Ramp graphs

Because the step frequency changes *per step* the frequency does not go up or down linearly. Here is a typical graph of the step frequency (Vertical) against time (Horizontal).



If there are not enough steps to reach the operating frequency the Gertbot starts ramping down early. This is required otherwise the motor will not be able to stop with the specified minimum step rate. The following is the graph of such a step sequence:



7.9 Corner case ramping behavior

When using ramping there are a number of operating cases the user has to be aware of:

- On a 'stop' command (normal, emergency or end-stop) the stepper motor is stopped right then and there. No ramping down takes place!
- No new step command should be giving whilst a previous one is still in operation. If so the stepping process starts immediately with the (slow) start frequency.
- When running at the operating frequency a new frequency command will take effect immediately. Thus no ramping up (if the new frequency is higher) or ramping down (if the new frequency is lower) to the new frequency will take place.

Motor error.

The user can program the following responses:

- Ignore error: The controller takes no further action.
- Stop channel: Stop the channel with the error.
(This is not available for stepper motors)
- Stop channel pair: Stop both channels of the motor controller.
- Stop board: Stop all motor controllers of the board (four channels).
- Stop system: Stop all motors on all boards.


Code	Error handling
0000	No error propagation
0001	Stop channels A,B,C,D
0010	Stop channel pair A&B (C&D)
0011	Stop board (A-D)
0100	Stop system (A-D on all boards)
<others>	<Unused>

7.10 DC/Brushed Pulse Width Modulation Motor Frequency

0xA0 0x04 <id> <MS> <LS> 0x50

Pulse Width modulation (PWM) is a technique used to control the speed of brushed motors. Instead of lowering the voltage, the motor controller provides power for a short period of time and then removes the power. Because of the inherent slow mechanical response of the motor it will run slower. In fact the mechanical behavior is better than with a lower voltage as the torque of a 10% PWM driven motor is higher than from a motor with only 10% of its voltage applied.

This command sets the PWM frequency used in brushed mode. The PWM causes pulsed signals to arrive at your motor. The coil in your motor is an inductor and pulses with an inductor can cause havoc if you don't know what you are doing. (see also § 16.6 *Inductors*.) Working with pulses and an inductor can cause very high voltage. Although the H-bridges are somewhat protected, they cannot withstand infinite voltages. So always be careful when using PWM. If you set the duty cycle to 100% there are no pulses and you can reasonably safely connect a DC motor.




The frequency must be between 10Hz and 30 KHz. If you change the brushed frequency the program will set the corresponding duty cycle for you. You can change the duty cycle whilst the motor is running.

Do not use a low frequency with big DC-brushed motors as it will cause extreme high inrush currents and that is likely to trip the over current protection. It will also make the controllers very hot especially if you disable the high current trip. See also §13.3 Brushed motor start/stop

7.11 Brushed Motor Duty Cycle

0xA0 0x05 <id> <MS> <LS> 0x50

This command sets the Pulse Width modulation (PWM) duty cycle used in brushed mode. The value must be between 0 and 1000. The duty cycle is specified in step of 1/1000 of 100%. Thus 100 is 10%, 500 is 50% etc. Setting a duty cycle of 100% (0xA0 0x05 <id> 0x03 0xE8 0x50) gives a signal which is constantly high (DC output) on the motor pins⁵.



The duty cycle is time-A divided by time-B. The picture above shows a duty cycle of 25%. (0xA0 0x05 <id> 0x00 0xFA 0x50). The duty cycle is maintained even if you change the frequency.

Default (after enabling) the duty-cycle for a brushed motor is set 100% by the system.

Unfortunately the hardware does not allow the duty cycle and the frequency to be independently set. Thus the Gertbot updates the duty cycle after a frequency change. As a consequence the duty cycle can be off

⁵ Unless you start rapidly switching your motors on/off or forward/backwards.

the requested value for a few micro seconds after changing the frequency. There is currently no way around this.

7.12 Start/stop Brushed Motor

0xA0 0x06 <id> <mode> 0x50

This command starts a brushed motor in either direction or stops it. You can start a brushed motor only if:

- You have set the mode to brushed
- You have set a frequency.
- The HALT line is not active
- You have no end-stops enabled or the end-stop in the direction you are moving is enabled but not active.
- You have correctly connected power and a brushed motor.

The direction (or stop) is set by the LS 4 bits of the command. Of the sixteen possible values three are used:

0x0 : Stop the motor

0x1 : Run in the A direction

0x2 : Run in the B direction

The other values are served for future use.

To make the motor go into a specific direction one output is set high and the other remains low. The following table shows the power on the motor control pins in relation to Run-A and Run-B:

Mode		A1, B1, C1, D1	A2, B2, C2, D2
0x0	Off	Low (Gnd)	Low (Gnd)
0x1	Run A	High (V motor)	Low (Gnd)
0x2	Run B	Low (Gnd)	High (V motor)

Soft start/stop

To prevent large in-rush currents the Gertbot supports soft-starting. For details about soft-starting see § **13.3 Brushed motor** start. There are sixteen soft start (ramp-up) values. The following table shows the soft-start value and the start-up time in seconds.

Code	Time	Code	Time	Code	Time	Code	Time
0x0	Off	0x4	0.75	0x8	1.75	0xC	3
0x1	0.1	0x5	1.0	0x9	2	0xD	4
0x2	0.25	0x6	1.25	0xA	2.25	0xE	5
0x3	0.5	0x7	1.5	0xB	2.5	0xF	7

Soft start time in seconds.

To start multiple motors at the same time use the 'sync' command system. See *7.25.1 Board Synchronous command mode*.

The 'linear' stop command is an exception in that it is also used to stop stepper motors. See also *7.14 Stepper motor* take steps.

Example start command:

0xA0 0x06 0x01 0x71 0x50 : Start board 0 motor 1 in direction A, ramp-up in 1 second.

7.13 Read error status

0xA0 0x07 <id> 0x50 0x50 0x50 0x50

The system keeps track of the last 16 errors. This command will return the status of the most recent error. If there are no (more) errors the return value will be 0. This command will return 4 bytes.

The first byte is the original ID.

The second byte is 0x06

Bytes three and four are the MS & LS value of the error code.

See appendix A for a full list of error codes.

As the command returns 4 bytes it must be followed by at least 4 bytes of 0x50.

7.14 Stepper motor take steps

0xA0 0x08 <id> <MS><MM><LS> 0x50

This command specifies how many steps a stepper motor should take. The value from the three bytes is a signed value between -8388607 and 8388607. A positive value moves the motor in direction A, a negative value towards B. You can start a stepper motor only if:

- You have set the mode to one of the stepping modes.
- You have set a frequency.
- The HALT line is not active
- You have no end-stops enabled or the end-stop in the direction you are moving is enabled but not active.
- You have correctly connected power and a stepper motor.

Once the number of steps have been taken the motor will stop but the current (power) will remain on the motor windings, holding the rotor anchored through the magnetic force. A new 'take steps' command will replace a command in progress.

A value of 0 will stop the motor at the end of the next step but the current (power) will remain on the motor, holding the rotor anchored. There is a second way of stopping a stepper motor: using the **Stop brushed motor** command. The difference is that the power is removed from the stepper motor coil and thus the rotor will not be anchored. As a result the rotor may change position if there is enough external force applied to it. This will result in the loss of system integrity.

Remaining steps.

When a stepper motor is stopped or when it receives a new command before it has finished the previous command, the system makes a copy of the remaining step counter. This value can be read by the user and can be useful in retaining the system integrity. The system has only one storage location for the number of remaining steps thus any new step will cause the loss of the previous value. The user can send multiple stop commands as the "remaining steps value" is not overwritten when the system is already halted.

If the 'attention' line is set to indicate 'steps-done' it will go low as soon as the step command is started. It will go high again when all stepper motors are done.

To start multiple motors at the same time use the 'sync' command system. See 7.25.1 *Board Synchronous command mode*.

Some examples:

100 steps in direction A:

- A0 08 00 **00 00 64** 05 (Stepper motor on A1..B2)
 - A0 08 02 **00 00 64** 05 (Stepper motor on C1..D2)
- (The bold part is the number of steps)

To step in the opposite direction use minus 100:

- A0 08 00 **FF FF 9C** 05
- A0 08 02 **FF FF 9C** 05

If you have given a large number of steps and want the system to stop send a step value of 0:

- A0 08 00 **00 00 00** 05 (Stop motor on A1..B2)
- A0 08 02 **00 00 00** 05 (Stop motor on C1..D2)

The motor will stop but the power will remain on the stator.

Or you can send a 'DC stop' command:

- 0xA0 0x06 0x00 0x00 0x50: Stop board 0 motor 0.

The motor will stop and the power will be removed from the stator.

Note: Even a motor running at the maximum stepper frequency of 5KHz will need ~28 minutes to take 8388607 steps.


7.15 Stepper Motor Step Frequency

0xA0 0x08 <id> <MS><MM><LS> 0x50


This command specifies the step frequency. The minimum frequency is 1/16 Hz (1 step every 16 seconds). The maximum frequency is 5000 Hz. The value passed in the command, is the frequency you want multiplied by 256. Thus the minimum value you should send is 0x000010, the maximum value is 0x138800.

It is not always possible to set the exact frequency but in all cases the real stepper frequency is better than 0.02% accurate.

The figures below show how the step frequency is related to the step waveforms.



Step frequency mode 2



Step frequency mode 3

Some examples:

```

10.5 Hz :   10.5*256   = 2688   = 0x00 0x0A 0x80
571.7 Hz :  571.7 *256 = 146355 = 0x02 0x3B 0xB3
1500 Hz :   1500*256   = 384000 = 0x05 0xDC 0x00

```

For more details about setting or changing the frequency see § **11.3 Frequency**.

7.16 Stepper Motor Ramping

0xA0 0x29 <id> <SSMS> <SSMM> <SSLS> <RATEMS> <RATEMM> <RATELS> 0x50

This command specifies how a stepper motor should ramp-up or down. It is specified using two parameters:

- Start/stop frequency
- Rate of change

Start/stop frequency.

The start/stop frequency is the frequency/speed at which the stepper motor starts and stops operating. e.g. 10 means it immediately starts taking steps at a speed of 10 Hz. It also is the frequency/speed at which the motor stops.

Rate of change.

The rate of change specifies how much the frequency will change *each step*. e.g. a value of 1 means the frequency will change by 1 Hz each step. The rate of change has a maximum value

For both values the minimum frequency is 1/16 Hz (1 step every 16 seconds). The maximum frequency is 5000 Hz. The value passed in the command, is the frequency you want multiplied by 256. Thus the minimum value you should send is 0x000010, the maximum value is 0x138800.

Additionally the rate of change must not be greater then 10% of the operating frequency.

7.17 Stop all

0xA0 0x0A 0x81 0x50

This command stops all motors on all boards. In contrast to an emergency stop all the stepper motors will remain powered.

7.18 Switch open drain

0xA0 0x0B <id> <on/off> 0x50

This command activates or de-activates one of the open drain outputs on a board. As there are only two open drain per board the valid id values are 0,1,4,5,8,9,12,13. The on/off byte can be 0x00 (open drain off) or 0x01 (open drain on). Due to the nature of an open drain output *off* means **no current** and the open drain output is high

7.19 Set DAC

0xA0 0x0C <id> > <MS ><LS> 0x50

This command writes a value to the on-board DAC converter. As there are only two DACs per board the valid id values are 0,1,4,5,8,9,12,13. The current DAC is 12 bits Therefore the upper 4 bits of the 16-bit value are ignored.

Warning: the board uses the Digital-to-Analog converter inside the Atmel SAM32 chip. However these 12-bit DAC's do not have the full 3.3V voltage range. The range is from maximum ~2.75 volts to a minimum of ~0.66 volts.

7.20 Read ADC

0xA0 0x0D <id> > <MS ><LS> 0x50 0x50 0x50 0x50

This command reads a value from the on-board ADC converter. The returned value is unsigned. As the current ADC is 12 bits the upper 4 bits of the return value are always zero. This command will return 4 bytes:

The first byte is the original id.

The second byte is 0x0D

Bytes three and four are the MS & LS value of the ADC.

As the command returns 4 bytes it must be followed by at least 4 bytes of 0x50.

The ADC converter is operating in continuous conversion mode. This means it reads a new value every millisecond and the value is stored. The value returned will be the last store value which can be up to 1 millisecond old.

7.21 Read I/O

0xA0 0x0E <id> 0x50 0x50 0x50 0x50 0x50

This command returns the status of all expansion pins. To allow space for future boards with more I/O the command has 3 bytes but the MS byte is currently unused and always returns 0x00.

MS byte bit	From	MM byte bit	From	LS byte bit	From
7	-	7	DAC1	7	EXT7
6	-	6	DAC0	6	EXT6
5	-	5	ADC3	5	EXT5
4	-	4	ADC2	4	EXT4
3	-	3	ADC1	3	EXT3
2	-	2	ADC0	2	EXT2
1	-	1	Spare1	1	EXT1
0	-	0	Spare0	0	EXT0

Read input byte association table

The command does NOT check which pins are enabled as input. It returns the raw data read. As such you get the status of special function pins as well. Note that the return status of an analog pin (ADC/DAC) is undefined. This command will return 5 bytes:

The first byte is the original id.

The second byte is 0x0E

Bytes three, four and five are the MS, MM & LS values read.

As the command returns 5 bytes it must be followed by at least 5 bytes of 0x50.

7.22 Write I/O

0xA0 0x0F <id> <MS><MM><LS> 0x50

This command sets the status of the user pins on the expansion connector. To allow space for future boards with more I/O the command has 3 bytes but the MS byte is currently unused. Write to pins which are NOT defined as output pins are ignored.

MS byte bit	To	MM byte bit	To	LS byte bit	To
7	-	7	DAC1	7	EXT7
6	-	6	DAC0	6	EXT6
5	-	5	ADC3	5	EXT5
4	-	4	ADC2	4	EXT4
3	-	3	ADC1	3	EXT3
2	-	2	ADC0	2	EXT2
1	-	1	Spare1	1	EXT1
0	-	0	Spare0	0	EXT0

Write output byte association table

7.23 Set I/O

0xA0 0x10 <id> <MS><MM><LS> 0x50

This command sets unused pins on the expansion connector to input or output. To allow space for future boards with more I/O the command has 3 bytes but the MS byte is currently unused. The following table shows which pins on the expansion connect are controller by which bit.

MS byte bit	Controls	MM byte bit	Controls	LS byte bit	Controls
7	-	7	DAC1	7	EXT7
6	-	6	DAC0	6	EXT6
5	-	5	ADC3	5	EXT5
4	-	4	ADC2	4	EXT4
3	-	3	ADC1	3	EXT3
2	-	2	ADC0	2	EXT2
1	-	1	Spare1	1	EXT1
0	-	0	Spare0	0	EXT0

Set I/O byte association table

Setting a bit to 1 makes the pin an input. Setting a bit to 0 makes the pin an output.

The command has no effect on pins which are assigned a function. Thus pins which are set as end-stop will remain operating as a digital input, pins which are set as ADC will remain operating as analog input, and pins set as DAC will remain operating as analog output. In effect, to use a pin for input or output you must *first* disable its special operating mode. That must be done with a separate command. The following table lists how to make the pins available for input/output mode.

Pin	How to reclaim for user access
EXT0	Disable motor 0 end-stop A
EXT1	Disable motor 0 end-stop B
EXT2	Disable motor 1 end-stop A or use motors 0/1 as stepper
EXT3	Disable motor 1 end-stop B or use motors 0/1 as stepper
EXT4	Disable motor 2 end-stop A
EXT5	Disable motor 2 end-stop B
EXT6	Disable motor 3 end-stop A or use motors 2/3 as stepper
EXT7	Disable motor 3 end-stop B or use motors 2/3 as stepper
ADC0	Disable ADC0 channel
ADC1	Disable ADC1 channel
ADC2	Disable ADC2 channel
ADC3	Disable ADC3 channel
DAC0	Disable DAC0 channel
DAC1	Disable DAC1 channel
HALT	<i>Cannot be reclaimed</i>

Expansion connector pin reclaim table

7.24 Set ADC/DAC

0xA0 0x11 <id> > <ADC><DAC> 0x50

This command enables or disables the on-board ADC and DAC channels. A reason to disable a channel is to use the pin on the expansion connector for user input or output.

The LS 4 bits of the ADC byte enable or disable an ADC channel. Bit 0 enables/disables ADC0, bit 1 enables/disables ADC1 etc. If the bit is set (high) the ADC channel is enabled. If the bit is clear the ADC channel is disabled.

The LS 2 bits of the DAC byte enable or disable a DAC channel. Bit 0 enables/disables DAC0, bit 1 enables/disables DAC1. If the bit is set (high) the DAC channel is enabled. If the bit is clear the DAC channel is disabled.

All unused bits are reserved for more ADC/DAC channels in the future.

7.25 Board configure

0xA0 0x12 <id> <MS><MM><LS> 0x50

This commands configures a board for various operating modes. Currently there are three board features which can be set:

- Synchronous mode
- Attention signal mode
- Channel error mode

7.25.1 Board Synchronous command mode.

If bit 0 of the LS byte is set the board works in synchronous command mode. At the moment direct stepper motor commands have the same behavior as normal stepper commands in that a new command replaces a previous, possible pending command. Thus a previous command can be overruled and replace with a new command if it has not yet finished. Synchronous mode for quadrature encoder goto-commands is not yet available.

7.25.2 'Attention' signal mode.

'Attention' is a signal shared between all boards but also goes to the Raspberry-Pi GPIO pin 22. A controller should only pull the line *low*.

Code	Attention signal mode
000	Off (=High)
001	Low as long as a stepper motor is running
others	<reserved for future use>

As the attention line is shared between all motors it will only go high if nobody pulls it low. So for the mode 001 this means the line will go high if all stepper motors have stopped running. (That is: only for motors on those boards which have their attention line mode set to 001). The status of the stepper motors is checked every millisecond. Thus there may be a delay of up to 1 millisecond between the last stepper motor stopping and the attention line going low.

The attention signal operating mode is placed in bits 1-3 of the LS byte.

For the attention line to work correctly, you must first set the mode, *then* start the stepper motors. If you set the mode to 1 and the stepper motors are already running the line is not updated.

7.25.3 Channel error mode.

The channel error mode determines what to do if an error is detected. For details see § 0 *Ramp down*:

Ramp-down begins when there are a limited number of steps still to take. The Gertbot software calculates the exact position (number of remaining steps still to take) where this process is started.

5. Each *step* the frequency decrements with the rate of change
6. Once the start/stop frequency has been reached it stays at the frequency.

At that moment the ramp-down has finished. That will coincides with the moment that there are no more steps to take.

The algorithm has some safeguards:

It will not step faster than the specified operating frequency

It will not step slower than the specified start/stop frequency


If there are not enough steps to take, the stepper motor might not get to the operating frequency. An extreme example would be where the user specifies only a single step. That step will then only be taken with the start/stop frequency.

7.26 Ramp graphs

Because the step frequency changes *per step* the frequency does not go up or down linearly. Here is a typical graph of the step frequency (Vertical) against time (Horizontal).



If there are not enough steps to reach the operating frequency the Gertbot starts ramping down early. This is required otherwise the motor will not be able to stop with the specified minimum step rate. The following is the graph of such a step sequence:



7.27 Corner case ramping behavior

When using ramping there are a number of operating cases the user has to be aware of:

- On a 'stop' command (normal, emergency or end-stop) the stepper motor is stopped right then and there. No ramping down takes place!
- No new step command should be giving whilst a previous one is still in operation. If so the stepping process starts immediately with the (slow) start frequency.
- When running at the operating frequency a new frequency command will take effect immediately. Thus no ramping up (if the new frequency is higher) or ramping down (if the new frequency is lower) to the new frequency will take place.

Motor error.

7.27.1 Board configure command overview.

The table below shows where all the board configure bits reside in the three bytes.

MS byte bit	Controls	MM byte bit	Controls	LS byte bit	Controls
7	-	7	Error chan. D bit 2	7	Error chan. B bit 0
6	-	6	Error chan. D bit 1	6	Error chan. A bit 2
5	-	5	Error chan. D bit 0	5	Error chan. A bit 1
4	-	4	Error chan. C bit 2	4	Error chan. A bit 0
3	-	3	Error chan. C bit 1	3	Attention mode bit 2
2	-	2	Error chan. C bit 0	2	Attention mode bit 1
1	-	1	Error chan. B bit 2	1	Attention mode bit 0
0	-	0	Error chan. B bit 1	0	Sync mode

Board configure command table

The MS byte of this command is currently unused.

7.28 Read board status

0xA0 0x03 <id> <MS><MM><LS> 0x50 0x50 0x50 0x50 0x50

This commands returns some status information of the board. The following table shows what the return status bits represent.

MS byte bit	Value	MM byte bit	Value	LS byte bit	Value
7	0	7	0	7	ES7
6	0	6	0	6	ES6
5	0	5	ATTn	5	ES5
4	0	4	HALT	4	ES4
3	0	3	ENB_D	3	ES3
2	0	2	ENB_C	2	ES2
1	0	1	ENB_B	1	ES1
0	0	0	ENB_A	0	ES0

System status byte association table

This command will return 5 bytes:

The first byte is the original id.

The second byte is 0x03

Bytes three, four and five are the MS, MM & LS values read.

The status bits are such that a *high* bit indicates a special or error condition.

The ES0-ES7 lines indicate the end-stop active values. If high the end-stop is activated (and hopefully the motor has been stopped). On the board an end-stop signal can be active high or active low. The micro controller takes that into account when producing the board status bits and corrects the polarity. Thus a high status bits always means an active end-stop.

The ENB_A..ENB_D status bits are the status of the motors controller error lines. High (1) means an error. You are unlikely to see these lines active when the current is too high as the controller is immediately switched off. This means that if you read one of these lines as high there is a high probability that the chip is too hot. <TO DO: latch A-D error status bits>

Low (0) means no error. (Note that the ENB_AB and ENB_CD line themselves are active low). For details see chapter **0 Ramp down:**

Ramp-down begins when there are a limited number of steps still to take. The Gertbot software calculates the exact position (number of remaining steps still to take) where this process is started.

7. Each **step** the frequency decrements with the rate of change
8. Once the start/stop frequency has been reached it stays at the frequency.

At that moment the ramp-down has finished. That will coincide with the moment that there are no more steps to take.


The algorithm has some safeguards:

- It will not step faster than the specified operating frequency
- It will not step slower than the specified start/stop frequency


If there are not enough steps to take, the stepper motor might not get to the operating frequency. An extreme example would be where the user specifies only a single step. That step will then only be taken with the start/stop frequency.

7.29 Ramp graphs

Because the step frequency changes *per step* the frequency does not go up or down linearly. Here is a typical graph of the step frequency (Vertical) against time (Horizontal).



If there are not enough steps to reach the operating frequency the Gertbot starts ramping down early. This is required otherwise the motor will not be able to stop with the specified minimum step rate. The following is the graph of such a step sequence:



7.30 Corner case ramping behavior

When using ramping there are a number of operating cases the user has to be aware of:

- On a 'stop' command (normal, emergency or end-stop) the stepper motor is stopped right then and there. No ramping down takes place!
- No new step command should be giving whilst a previous one is still in operation. If so the stepping process starts immediately with the (slow) start frequency.

- When running at the operating frequency a new frequency command will take effect immediately. Thus no ramping up (if the new frequency is higher) or ramping down (if the new frequency is lower) to the new frequency will take place.

Motor error.

The HALTED bit is high if the HALTn line is active and the system is in the halted state. (Note that the Halt line itself is active low).

The ATTN status bit reflects the actual status of the ATTN line.

As the command returns 5 bytes it must be followed by at least 5 bytes of 0x50.

7.31 Read motor status

0xA0 0x14 <id> 0x50...0x50

This commands returns some status information of a motor.

This command will return 16 bytes:

The first byte is the original id.
 The second byte is 0x03
 Bytes 2..16 have the motor status packed in them. .

The following code show how to extract the information:

This C-code extracts the information:

```
status->mode           =rec[2] & 0x0F;
status->ramp            =(rec[2] & 0xF0)>>4;
status->endstop         =rec[3] & 0x3;
status->endstop_polarity=(rec[3] & 0xC)>>2;
status->move            =(rec[3] & 0xF0)>>4;
status->frequency       =(rec[4]<<16) + (rec[5]<<8)+rec[6];
status->duty_cycle      =(rec[7]<<8)+rec[8];
status->steps           =(rec[ 9]<<16) + (rec[10]<<8)+rec[11];
status->remainder      =(rec[12]<<16) + (rec[13]<<8)+rec[14];
```

7.32 Sync

0xA0 0x15 0x18 0x50

This command tells all boards to execute any outstanding 'sync' commands. For more information see: *§11.4 Synchronous operation.*

7.33 Poll

0xA0 0x16 <IG> 0x50 0x50 0x50 0x50

This command asks a board for its error status. The response is a single byte with the following fields:

Bit	Meaning if set
7	<not used>
6	<not used>
5	<not used>
4	<not used>
3	0
2	0
1	There are unread error messages
0	Halt line was activated

System status table

As the command returns 3 bytes it must be followed by at least 3 bytes of 0x50.

7.34 Power off / Emergency halt

0xA0 0x17 0x81 0x50

This command stops all motors on all boards and remove the power from them. It is the software equivalent of the **emergency stop**

7.35 Read back I/O configuration

0xA0 0x18 <id> 0x50...0x50

This command returns the operational status of the I/O pins in 16 bytes some of which are not yet used. It contains the mode of the pins (input, output or special function). If a pin is neither input nor output it is a special function. It also contains the state the output was set to: high or low.

The following code show how to extract the information:

```
status->adc_enable      = rec[2] & 0x0F;
status->dac_enable      = rec[3] & 0x03;
status->input_ports     = rec[6] | (rec[5]<<8);
status->output_ports    = rec[9] | (rec[8]<<8);
status->outputs_status  = rec[12] | (rec[11]<<8);
status->od              = rec[13] & 0x03;
```

As the command returns 16 bytes it must be followed by at least 16 bytes of 0x50.

7.36 Send DCC message

See § 8.1 DCC command.

7.37 DCC configuration

See § 8.2 DCC configure.

7.38 Read back Motor configuration

0xA0 0x1B <id> 0x50...0x50

This command returns the operational status of a motor in 13 bytes some of which are not yet used. The following code show how to extract the information:

```

status->mode           =rec[2] & 0x0F;
status->step_pwr_off    =rec[2] & 0x10;
status->endmode         =rec[3] & 0xF;
status->short_hot_stop  =rec[3]>>4;
status->frequency       =(rec[4]<<16) + (rec[5]<<8)+rec[6];
status->duty_cycle      =(rec[7]<<8)+rec[8];
status->ramp_up          =(rec[9] & 0x0F);
status->ramp_down        =(rec[9] >>4);
status->ramp_halt        =(rec[10] & 0x0F);

```

As the command returns 13 bytes it must be followed by at least 13 bytes of 0x50.

7.39 Read back Motor Missed steps

0xA0 0x1C <id> 0x50...0x50

There are cases where a stepper motor command is prematurely ended. This can be a stop command, an emergency stop (Hot or short circuit) or a follow up stepper command whilst the previous has not yet finished. In that case the Gertbot keeps a copy of the amount of remaining steps.

There is only one copy, thus if a new value must be stored the previous one is lost. This can only happen if after 'step' command arrives as the old value is NOT overwritten if the motor has already stopped. Thus you can safely give multiple stop or emergency stop commands and still read back the value.

When asking a the missed step from a motor which is NOT in stepper mode will return the value 0 .

This command returns the missed steps count in 8 bytes. The first two are the usual reply: the ID followed by the command byte itself. Next comes 6 bytes with the counter value. Currently only the first three are used.

```
missed_steps = (rec[2]<<16) + (rec[3]<<8)+rec[4];
```

As the command returns 8 bytes it must be followed by at least 8 bytes of 0x50.

7.40 Set Ramp rate

0xA0 0x1D <down, up> <halt> 0x50

This command set the three different ramp rates.

- The first byte LS 4 bits hold the up-ramp time.
- The first byte MS 4 bits hold the down-ramp time.
- The second byte LS 3 bits hold the stop-ramp time.

Beware that a 'stop' and an 'emergency stop' are handled different. A normal stop command will use the ramp-down time. With an emergency stop the power of all motors is removed immediately.

For more details see §13.3 *Brushed motor start/stop*.

7.41 Set baud rate

0xA0 0x 22 <baud> 0x50

This command is only available in software version 2.4 and higher. It allows the user to change the baud rate. Five baud rate values are available:

```

0 = 19200
1 = 38400
2 = 57600
3 = 115200

```

4 = 230400

The board has not been tested with baud rates above 56700 baud. At such high baud rates there is a much higher risk of “flooding” the system. It will cause commands to be lost if the input queue overflows. Furthermore it can take several commands before the system recovers from that.

7.42 Enable/disable quadrature encoder

0xA0 0x23 <id> <flags> <posMS> <posMM> <posLS> 0x50

This command enables or disables the quadrature encoder mode for a channel.

Bit 4 (0x10) of ‘flags’ is the enable/disable bit.

- If bit 4 is set the quadrature encoder is enabled.
- If bit 4 is clear the quadrature encoder is disabled.

Bit 1 (0x01) of ‘flags’ is the reverse bit. If you find that the ‘position’ is decrementing when doing a MOVE-A flip the bit to correct that. It also possible two swap the two wires of the quadrature encoder sensor around to get the same effect but setting this bit might be easier.

The pos bytes sets the current position. Just as with the stepper count the three bytes make up a 24 bit signed number in the range of -4194303 to +4194303.

For more information about using the quadrature encoder see § 9 *Quadrature encoder*.

7.43 Read quadrature encoder

0xA0 0x24<id> 0x50 0x50 0x50 0x50 0x50 0x50

This command returns 7 bytes. This first two are the usual command & id bytes. Then comes the position in three bytes (MS first signed). last come two bytes holding a 16 bit error counter (MS first, unsigned)

Note that the position is a *signed* 24 bit number. If you take the number into a 32-bit variable do not forget to sign extend it!

The error counter is a saturating 16 bit counter.

For more information about using the quadrature encoder see § 9 *Quadrature encoder*.

7.44 quadrature encoder goto

0xA0 0x25<id> <posMS> <posMM> <posLS> <DC ms> <DC ls> 0x50

Starts the brushed motor to reach the indicated position. The DC is the duty cycle at which the motor will run. The duty cycle parameter works identical to the Brushed motor duty cycle command. (See § 7.11 *Brushed Motor Duty Cycle*)

For more information about using the quadrature encoder see § 9 *Quadrature encoder*.

7.45 Quadrature control

0xA0 0x26<id> <flags> <maxMS> <maxMM> <maxLS>
 <minMS><minMM> <minLS>
 <distMS> <dist LS>
 <DCMS> <DCLS> 0x50

This commands set the limits and the ‘slow’ distance and speed for the quadrature encoder.

<flags> has three flag bits:

- bit 1 (0x02): Go slow. If this bit is set the motor will slow down when getting near to the max, min or got position.
- bit 2 (0x04): Max enable. If this bit is set the maximum limit is enabled.
- bit 3 (0x08): Min enable. If this bit is set the minimum limit is enabled.

The maximum and minimum position are each a 24-bit signed number.

The 'slow' distance is a 16 bit unsigned number.

The 'slow' speed is a two-byte duty-cycle value.

For more information about using the quadrature encoder see § 9 *Quadrature encoder*.

8 Digital Command Control

Digital Command Control (DCC) is a system to control model trains. The Gertbot was not originally design to perform this function but it turned out that the hardware and microcontroller where powerful enough to add this functionality. DCC mode can be set for each channel separately. This allows the user to have four independent DCC channels. But you can again mix-and-match. For example have two DCC channels and two analog channels.

The DCC mode has been tested with train equipment donated by Hornby (Thank you Ken!). There is a rudimentary system for playing with the DCC system in the Gertbot GUI but to use the Gertbot with a real train emplacement a new GUI should be written. A task I have to leave for others due to a lack of time.

Format

DCC commands are send as packets. There are rules how to send packet which you do not need to know as the Gertbot will take care of that. The Gertbot will also take care of repeating the packets. Beware that the system does not infinitely repeat the packets as some controller do. It send a packet N times (The value of N is programmable) and then no longer. If you want commands to be send repeatedly every 10 seconds you have to program your computer to do that. There are two DCC commands. One to send packets, the other to configure the Gertbot DCC parameters.

If an output is set up in DCC mode the user can send command to the board which will then be transferred to the outputs. A DCC command is between 3 and 6 bytes long, where the last byte is a checksum byte. The Gertbot will calculate the checksum byte so you *should not send that*. Which means DCC commands for the Gertbot are 2 .. 5 bytes long. To keep the software in the controller simple a DCC command is always send as 10 bytes:

Destination.

The DCC command are unique in one other way: You do not send commands to a specific channel. DCC commands can be send to any or all four channels simultaneous. The MS bits of the format byte indicate to which channel the message should be sent:

Bit 7 set: send to channel 3.

Bit 6 set: send to channel 2.

Bit 5 set: send to channel 1.

Bit 4 set: send to channel 0.

Thus when setting all four bits the message is sent to *all four channel simultaneously*. If an output is not configured for DCC mod the data is not send to that output. The destination is silently ignored. *This is the*

only time that no error message is generated although an illegal command has been sent. It allows the user to send DCC commands everywhere all the time.

The LS 4 bits of the format byte indicate the message length. This is the number of bytes which will be send to the output. This is NOT the number of bytes send to the Gertbot. You always send 10 bytes to the Gertbot. You do not have to send the checksum byte as that is calculated by the Gertbot and it is automatically appended. You also do not have to repeat the message as the Gertbot will send the message a number of times.

Pacing.

The DCC output rate depends on the number of times a command is repeated. The raw rate is about 6.3Kbits/sec. If each message is repeated four time that drops to ~1500 bits/seconds. The data rate to the Gertbot is 57Kbits/sec. Thus you can send commands *thirty* faster to the Gertbot then it can output them. Thus there is the potential of overloading the system. The Gertbot checks its output queue to see if a new message will fit. (The current queue size is 128 bytes). If there is not enough space the whole message is discarded and an error is generated. Thus you do not have to worry about partially messages upsetting the system.

No synchronous output.

The four output channels are treated as independent entities. Thus it is not possible to connect the four output to the same track. If a higher current is required you must make a physical modification to the board connect the output drivers in parallel. For information how to do that see the Gertbot Advanced Guide.

8.1 DCC command

0xA0 0x19 <id> <format> <address> <data> <data><data><data> 0x50

<format> has the destination in the MS 4 bits and the data length in the LS 4 bits.

Examples:

Send 0x03, 0x40 to channels 0 and 1 on board 0:

0x0A 0x19 0x00 0x32 0x03 0x40 0x00 0x00 0x00 0x50

Send 0x10, 0x11, 0x12, 0x13, 0x14 to all four channels on board 1:

0x0A 0x19 0x04 0xF5 0x10 0x11 0x12 0x13 0x14 0x50

8.2 DCC configure

0xA0 0x1A <id> <repeat> <preamble> <DC> <flags>0x50

This command is used for DCC configuration.

<repeat> is the number of times a command is repeated. Values under 4 are not recommended whilst very high values reduce the data rate. Range is 4..255

<preamble> is the number of preamble bits (number of high bits at the start of each packet). This value must be >= 14!. Range 0-255


<DC> this is used to generate a DC offset on the output. This is not fully implemented yet. Beware that not all DCC decoder can cope with DC level produced in this way.

< flags > If the LS bit is set the system will no longer send idle packets when there is no data. (In revision before 2.6 it will still send one idle packet after each command). The complete

suppression of idle packets seems to be a requirement when sending DCC reset and program-commands to the controller.

8.3 Connecting it up.

To connect up a DCC system to a railway use the same diagram as connecting brushed motors:



Instead of a motor use the two connections of your railroad track. The DCC system is polarity agnostic. That is: it does not matter to which rail you connect the A1 or A2 wires. For the power you can should use an external 15V DC supply. As with the other motors you can use a different supply for the two output groups.

Higher current.

For DCC mode you can also achieve a higher current output then 2.5Amps. For this you must connect multiple output channels in parallel. Follow the connection scheme as described for brushed motors in the Gertbot Advanced Guide. If all four channels work in parallel the board can handle 10Amps. Note that this is the only way in which you can guarantee that all outputs are in perfect synchronisation.

9 Quadrature encoder

The software release revision 2.5 and higher supports quadrature encoders. The quadrature encoder shares its pins with the end-stops. This means you can have either end-stops or a quadrature encoder. Not both. To compensate for the loss of end-stops the user can set a maximum and minimum position. The motor will not move beyond the specified limits⁶.

The quadrature encoder is only usable with brushed motors.

More information about how a quadrature encoder works is expected to be added to section § 16 *Appendix B: Technology*. in due time.

9.1 Maximum operating frequency.

The quadrature encoder is read every millisecond. This means that encoders which change faster than that rate are not supported. The system counts any illegal transition. Thus a non-zero error counter indicates that the encoder is faulty or running too fast.

9.2 Position & direction

The system maintains internally a 24-bit signed position counter for each motor. The user is responsible to make sure the quadrature encoder increments when the motor runs in direction “A”. If the quadrature encoder decrements there are two solutions:

- Set up⁷ the quadrature encoder with the ‘inverse’ bit.
- Swap the two sensor wires around.

The Gertbot GUI can be used to verify this.

When the quadrature mod is enabled, the position function is continuously running. Also when the motor is stopped. Thus if an external force moves the system, the quadrature encode will keep track of where it is.

9.3 Operation.

In contrast to the stepper motor the quadrature encoder software is mainly designed to control a brushed motor to move to a specified ‘position’. After setting the start position the user can give a “go-to X” command. From the current position and the indicated position the Gertbot knows which direction to start the motor. The end speed is set by the duty cycle parameter of the go-to command. The duty cycle parameter works identical to the Brushed motor duty cycle command. (See § 7.11 *Brushed Motor Duty Cycle*)

9.4 Limits.

As mentioned before: when the quadrature encoder is enabled you no longer can have end-stops. To give back some control the user can specify a maximum and minimum position. As long as the ‘go-to’ command is used, the motor will not get beyond those positions.

At the moment the normal ‘Start brushed motor’ command does not check the quadrature encoder position. Using that command you can still force the motor when it is already in (or beyond) the

⁶ Provided you use the quadrature go-to command.

⁷ See § 5.33 Enable/disable quadrature encoder.

maximum or minimum position. (But it will run only for a short period as the quadrature encoder will detect this and stop it again).

9.5 Overshoot, go-slow.

A brushed motor takes some time to stop. If no precautions are taken it is likely that the motor will overshoot the target position. To help the user with the complex system of reaching the endpoint in a smooth way the Gertbot has a feature called 'go-slow'. The go-slow feature changes the duty-cycle (speed) when the quadrature encoder detects that it gets near to the 'end-point'. The endpoint can be one of:

- The go-to position
- The maximum position
- The minimum position.

The user can control the following parameters of the 'go-slow' feature:


- go-slow flag
- go-slow distance
- go-slow speed

The go-slow flag enables the go-slow feature. If clear the system will not perform any go-slow actions.

The go-slow distance specifies the point at which the go-slow feature kick-in.

The go-slow speed is the duty-cycle used when going slow. The 'slow' duty cycle is set when the motor is 'distance' away from the end-point. The go-slow duty cycle will only be used if it is lower than the current value. It will never make the motor run faster.

The diagram below shows the areas where the motor will run slowly if this feature is enabled:



9.6 Ramp-up settings.

The quadrature encoder works with the 'brushed-motor-ramp-up' settings. It does NOT work with the ramp-down or halt settings as it does not know when to apply the settings in order not to overshoot the endpoint. Instead use the 'slow-go' and 'distance' settings to achieve a similar behavior.

10 Servo mode


In servo mode the Gertbot produces a 3V3 signal suited to control servo motors. **The servo control signal does NOT come out of the motor pins (A1,A2..D1,D2) but out of the *expansion* header.**

Servo control was introduced in revision 2.7. At this moment there are no C or Python driver routines for servo control yet.

In order to connect a servo look at paragraph **4.10 Connecting servos**.

10.1 Signal

The servo control signal is a pulse is repeated every 25 milliseconds (40 Hz) and the width of the pulse controls the servo. The standard specifies that the extreme (min/max) positions should correspond to a pulse width of resp 1 ms and 2 ms.



In the Gertbot the user specifies the servo position with a number in the range of 0 to 1000. Where 0 is the minimum position (1 millisecond pulse width) and 1000 is the maximum position (2 milliseconds pulse width).

Testing has found that many servo motors do not adhere to the standard 1..2ms range. Many were found to need less than a 1ms pulse to get to their minimum position. Likewise many needed a pulse width larger then 2ms to go to their maximum position.

Therefore the pulse width values can be changed using the ‘trim’ parameters.

- The minimum can be set between 250 microseconds and 1.5 milliseconds.
- The maximum can be set between 1.5 milliseconds and 3 milliseconds.


The servo position control is *not* affected by this. Thus 0 and 1000 are still the extreme min and max position values and 500 will *always* be the middle of the trim points.

10.2 Speed

The Gertbot can control the *minimum* speed at which the servo changes. This is set using the “Move-time” value. This time specifies the number of seconds it takes to get from one extreme to the other extreme position. The move-time is specified in tens of seconds. Thus a value of 200 means: it takes 20.0 seconds to move from one extreme to the other.

10.3 Ramping

On top of the slow movement the Gertbot offers 'ramping'. Ramping means that the servo motor does not abruptly starts or stops. This can be beneficial for camera movements as the video compression software works better if there are not abrupt changes. Ramping takes place at the beginning and at the end of a position change. Below is a typical ramp curve produced by the Gertbot where the pulse width is changed from 1.5 milliseconds to 2 milliseconds.



The Gertbot can NOT control the maximum speed as that depends on the servo motor. It can only slow the movement down.

Using slow movement and/or ramping can cause extra vibration with some servos as the servo motor is excited in small steps.

10.4 Commands

There are two servo command. One for configuration and one for position control.

Servo configure

**0xA0 0x27 <id> <Speed MS>, <speed LS>, <Ramp>, <Flags>,
<trim Min. MS> <Trim min. LS> <Trim Max MS> <Trim Max LS> 0x50**

Speed This is 16 bit value but must be in the range 0..1023. It specifies the time (in 0.1 second steps) the servo takes to move from the minimum position (0) to the maximum position(1000). Movements over a smaller distance will take proportional time.

Ramp This is an 8 bit value but must be in the range 0..128. It specifies the time (in 0.1 second steps) it takes to go from zero to the speed specified in 'speed' or from 'speed' back to zero. Ramping takes place at the start and at the end of a position change.

flags This is an 8 bit value. The flag parameter is currently unused. A future option is to invert the waveform which allows the Gerbot to drive an inverter amplifier.

Trim Min This is 16 bit value. This is the minimum pulse width generated when the position is set to zero. It can be set in the range of 250...1499.

Trim Max This is 16 bit value. This is the maximum pulse width generated when the position is set to 1000. It can be set in the range of 1501...3000.

Servo position

0xA0 0x28 <id> <Position MS> <Position LS> 0x50


Position This is 16 bit value but must be in the range 0..1000. It specifies the position the servo arm should take up.

11 Operating details

11.1 End-stops

Often a motor is controlling a mechanical part which is limited in its movement. In that case the motor should not move the mechanical part beyond a certain limit. Therefore there are switches (mechanical or optical) which tell the motor to stop moving in that direction. This is what is called an end-stop in this manual.

It is not possible in this manual to talk about the 'direction' of a motor. The direction depends on how the user connects the motor wires. By reversing the wires the 'direction' changes. Therefore I use the nomenclature A and B. When a motor is moving in direction 'A' it is stopped if end-stop condition 'A' is seen. The other end-stop (B) has no effect on the motor when it is moving in direction 'A'.



Each motor has been assigned two input pins which can be programmed as end-stops. If an end-stop is active the motor cannot be started to move further into the end-stop direction. If an end-stop becomes active and the motor is moving into its direction, the motor is stopped.

End-stops can be enabled, disabled and can be programmed as active high or active low.

The following table shows the relation between the motors, the end-stops, the inputs associated and the travel direction it guards.

Motor	End-stop	Pin	Brushed direction	Stepping Direction
0	A	Ext0	1 (binary 01)	Positive
0	B	Ext1	2 (binary 10)	Negative
1	A	Ext2	1 (binary 01)	-
1	B	Ext3	2 (binary 10)	-
2	A	Ext4	1 (binary 01)	Positive
2	B	Ext5	2 (binary 10)	Negative
3	A	Ext6	1 (binary 01)	-
3	B	Ext7	2 (binary 10)	-

End-stop association table.

The end-stop system works only if the user has set the motor direction correctly. The Gertbot associates a motor travel direction with an end-stop. Travel direction A means the motor is expected in due time to active end-stop A. If you find the motion is in the opposite direction there are two ways to remedy this:

1. You can swap the wires of the two end-stops A and B around.
2. You can invert the motor rotation direction.

You can change the direction of a brushed motor by swapping the two wires. You can change the direction of a stepper motor by changing multiple wires. See the operating manual of your stepper motor.

End-stop polarity

The end-stop inputs have a pull-up resistor. Thus if an end-stop is not connected it will read as high (1). From that it seems most convenient to use active-low end-stops. *However it is better to use active high end-stops.*

If possible you should always use active high end-stops. The reason is that if for some reason the wire between your end-stop switch and the board brakes, the end-stop will become high and thus indicate a stop. With an active low end-stop the motor will hit the switch which is no longer connected and keep traveling!

For more protection you can add a second switch after each electronic stop which is in series with the motor power. If the first switch fails the second one will cut off the power to your motor. But you then have to manually rotate the motor shaft to free the switch again.

If you don't need end-stops you can disable the function and use the pins as a general purpose I/O.

Brushed versus Stepper end-stops

The way the end-stops work depends on the motor operating mode.

For Stepper motors the status of the end-stop signal is checked just before a new step is to be taken. If the end-stop is found to be active the step is not taken and any further steps of the stepper motors are also cancelled.

For DC/Brushed motor the end-stop signals were implemented using an interrupt routine making the Gertbot respond extremely fast when an end-stop was activated. This mode was also shown to be very sensitive to any noise on the end-stop inputs. From version 2.4 onwards the interrupt mode is still supported but there is an additional mode where the input signals are filtered. Thus the signal has to be active for a certain amount of time before the CPU responds.

End-stop filter

For DC/Brushed mode the Gertbot software (revision 2.4 and higher) supports filtering on the end-stop inputs. There is an independent filter for each pin which checks the duration of the signal. The timer is implemented using an 'integrator' function. The signal is sampled every millisecond and a counter keeps track if the signal is active (the counter is incremented) or inactive (the counter is decremented). The end-stop is seen as 'triggered' if the counter reaches a certain threshold. The user can set threshold between 0 (filtering disabled) or 255 (signal must be active for 255 milliseconds). A filter value of 0 means the Gertbot uses the interrupt routine to stop the motor. This is compatible with SW versions before 2.4.

11.2 Halt

There is a common 'halt' line. If that is pulled low every CPU will remove the power from all motors and all activity will stop. The 'halt' line is common between all cascaded motor boards. The 'halt' line can be pulled low by the user or by the system itself. You are only allowed to pull this signal low (connect to ground). Note that you can not start any motor when the halt line is low.

The HALT input can be used to implement the 'big red emergency' button:



11.3 Frequency settings

The stepper motor frequency and the PWM frequency are programmable. Especially for the stepper motors it is important that you never get a pulse which is shorter than what the motor can respond to. If that happens the actual position of the motor will no longer corresponds to what the computer thinks it is. Special attention has been given to the code which sets the frequency so that a step pulse may be slightly longer then the programmed period, but it is never shorter. There is one exception to this rule: on an emergency HALT all power is removed from all motor simultaneously. This will cut short any step pulses in progress.

11.3.1 Jitter.

The PWM of the brushed motors is completely done by hardware timers. Thus they are very accurate. However the stepper motors are controlled by the CPU using interrupts. This means there is the probability that the pulse width will be slightly longer. This will happen if a stepper-timer interrupt arrives and at the same time the CPU is busy with a different interrupt routine or is running a critical section. If the other channels are NOT working in DCC mode measurements have shown the jitter to be smaller than 5µ seconds.

DCC mode.

When operating a channel in DCC mode the jitter on the other channel operating in stepper mode will increase. There is no hard figure also as the more channels operate in DCC mode the larger the jitter will be. If very accurate stepper times are required and DCC mode at the same time there are two solutions:

1. Keep the stepper frequency low so the relative error is not too big.
2. Purchase an additional Gertbot board. Run the DCC mode on one and the stepper modes on the other.

11.3.2 Accuracy.

The stepper motor frequency has been given a very wide range. This is so some applications can run their stepper motors at 5KHz. whilst others, e.g. who want to debug, want to run them at 0.25 Hz (1 step every 4 seconds). Therefore the step frequency is made a 24 bit parameter. The smallest possible step frequency is 1/16 Hz (One step every 16 seconds). The maximum is 5 KHz (5000 steps/sec). The frequency is implemented in three ranges and in each range the accuracy is better than 0.2%.

[the step frequency is send as a 16.8 integer. That is: you send a 24 bit number. The MS 16 bits are the integer part, the LS 8 bits are the fractional part. In practice this means that you multiply your frequency by 256 before you send it out. Thus a frequency of 5KHz is send as $5000 * 256 = 1280000$ (0x138800). 1/16 Hz is passed as $0.625 * 256 = 16$ (0x000010).]

The stepper frequency is better than 0.02% accurate. Also the stepper motors frequencies are all derived from the same master source clock but further work independent. This means that you can use the stepper frequencies to replace the Bresenham line drawing algorithm.

11.4 Synchronous operation

Especially with four boards and 16 motors it can take some time to send commands to all motors. Therefore the Gertbot has two ways of starting motors in almost perfect synchronisation.

11.4.1 Direct commands.

Direct commands are specifically added to support systems which produce individual "step" commands. Each command can make a stepper motor take between 1-7 steps in either direction. Currently there are two commands:

1. 0xA1 <start board 0>
2. 0xA4 <start board 0> <start board 1> <start board 2> <start board 3>

Direct commands are special in that they do NOT need a leading 0xA0 or a trailing 0x50!

The <start board x>command bytes are interpreted different for brushed and stepper motors.

This is the command byte interpretation for brushed motors:

Byte MS LS	Action
xxxxxx00	Motor 0 stop
xxxxxx01	Motor 0 run direction A
xxxxxx10	Motor 0 run direction B
xxxxxx11	Motor 0 no change
xxxx00xx	Motor 1 stop
xxxx01xx	Motor 1 run direction A
xxxx10xx	Motor 1 run direction B
xxxx11xx	Motor 1 no change
xx00xxxx	Motor 2 stop
xx01xxxx	Motor 2 run direction A
xx10xxxx	Motor 2 run direction B
xx11xxxx	Motor 2 no change
00xxxxxx	Motor 3 stop
01xxxxxx	Motor 3 run direction A
10xxxxxx	Motor 3 run direction B
11xxxxxx	Motor 3 no change

Below is the command byte interpretation for stepper motors. You can stop a motor, keep it unchanged or take between 1 and 7 steps in each direction

Byte		Action
MS	LS	
xxxx0000		Motor 0/1 stop
xxxx1000		Motor 0/1 no change
xxxx0SSS		Motor 0/1 SSS steps direction A (SSS = 1..7)
xxxx1SSS		Motor 0/1 SSS steps direction B (SSS = 1..7)
0000xxxx		Motor 2/3 stop
1000xxxx		Motor 2/3 no change
0SSSxxxx		Motor 2/3 SSS steps direction A (SSS = 1..7)
1SSSxxxx		Motor 2/3 SSS steps direction B (SSS = 1..7)

If you have a mixture of brushed and stepper motors connected to one board you can mix the commands bits of these two tables.

The baud rate is set to 57600 baud and it requires 20 baud clock cycles to transfer a direct command. This means you can send single step commands at maximum 2880 Hz to one board.

At the moment direct stepper motor commands have the same behavior as normal stepper commands in that *a new command replaces a previous, possible pending command*. Thus a previous command can be overruled and replace with a new command if it has not yet finished.

11.4.2 Synchronous commands

Currently only the motor start, stop and step commands can be executed synchronously.

The synchronous mode is enabled or disabled using the board setup command (See § 7.25 Board configure). In synchronous mode the execution of the two start/stop motor commands

- Start Brushed Motor (0xA0 0x06 <id> <mode> 0x50)
- Take steps (0xA0 0x08 <id> <MS><MM><LS> 0x50)


is postponed until a "sync" command arrives (0xA0 0x15 0x18 0x50). As you can see the Sync command has no identifier as it is acted upon by all boards simultaneous.

Thus you can send 'take steps' command to all stepper motors and then start them virtually at the same time using the 'sync' command. If you send multiple commands to the same motor, before the 'sync' is sent, only the last command is executed. All previous commands are lost.

There are some details to keep in mind:

- There will still be a small delay of max 4 micro seconds between the starting of the motors.
- The stepper motor **timer** is started on the sync command. The actual step will only take place after the stepper period has finished.

The diagram below shows what this implies:



12 Stepper motor ramping

In revision 2.8 a feature was added to dynamically change the step rate of stepper motors. This is referred to as stepper-ramping.

There was an issue that the Gertbot would immediately start stepping at the specified step frequency. Especially for bigger stepper motor this could cause problems and also they could not run at their maximum stepper frequency without additional software. Using software stepping meant that the user had no control of the exact number of steps taking.

12.1 Ramp parameters

In revision 2.8 a new command is added: stepper ramp control. This adds two more parameters which control the stepper motor.

- Start/stop frequency
- Rate of change

Start/stop frequency.

The start/stop frequency is the frequency/speed at which the stepper motor starts and stops operating. e.g. 10 means it immediately starts taking steps at a speed of 10 Hz. It also is the frequency/speed at which the motor stops.

Rate of change.

The rate of change specifies how much the frequency will change *each step*. e.g. a value of 1 means the frequency will change by 1 Hz each step.

The ramping algorithm is only enabled if *both* parameters are non-zero. To disable ramping again you can set either of them to zero.

12.2 Ramp behavior

Together with the step frequency and the number of steps to take there are now four parameters which control a step command:

- Number of steps to take
- Operating frequency
- Start/stop frequency
- Rate of change

The ramping algorithm works as follows:

Ramp up.

Ramp-up begins when the user gives a 'step' command.

1. The motor starts stepping using the start/stop frequency.
2. Each *step* the frequency increments with the rate of change
3. Once the operating frequency has been reached it stays at the frequency.

At that moment the ramp-up has finished.

Ramp down:

Ramp-down begins when there are a limited number of steps still to take. The Gertbot software calculates the exact position (number of remaining steps still to take) where this process is started.

9. Each *step* the frequency decrements with the rate of change
10. Once the start/stop frequency has been reached it stays at the frequency.

At that moment the ramp-down has finished. That will coincide with the moment that there are no more steps to take.

The algorithm has some safeguards:

- It will not step faster than the specified operating frequency
- It will not step slower than the specified start/stop frequency


If there are not enough steps to take, the stepper motor might not get to the operating frequency. An extreme example would be where the user specifies only a single step. That step will then only be taken with the start/stop frequency.

12.3 Ramp graphs

Because the step frequency changes *per step* the frequency does not go up or down linearly. Here is a typical graph of the step frequency (Vertical) against time (Horizontal).



If there are not enough steps to reach the operating frequency the Gertbot starts ramping down early. This is required otherwise the motor will not be able to stop with the specified minimum step rate. The following is the graph of such a step sequence:



12.4 Corner case ramping behavior

When using ramping there are a number of operating cases the user has to be aware of:

- On a 'stop' command (normal, emergency or end-stop) the stepper motor is stopped right then and there. No ramping down takes place!
- No new step command should be giving whilst a previous one is still in operation. If so the stepping process starts immediately with the (slow) start frequency.

- When running at the operating frequency a new frequency command will take effect immediately. Thus no ramping up (if the new frequency is higher) or ramping down (if the new frequency is lower) to the new frequency will take place.

13 Motor error

Each motor controller has two error outputs, one for each H-bridge. This output is pulled low by the motor controller itself when an error is detected. Possible causes for an error are:

- Current too high
- Temperature too high

An error condition ***always*** switches the motor controller channel ***off***. This safety measure can not be disabled. It reduced the risk of the controller getting damaged.

13.1 Reaction to an error

The motor error signals are connected to the processor. The user can program the controller to take various action if an error is seen:

- A. The error signal is ignored.
- B. The motor channel is switched off.
- C. The pair of channels is switched off.
- D. All four channels on the board are switched off.
- E. All channels on all boards are switched off.

A: Ignore error

This means the processor ignores the incoming error signal. Even if the processor ignores the error signal, the motor channels (H-bridge) will still be switched off. This can lead to oscillations. For details see *13.2 Oscillation..* It is not recommended to run in this mode, as your motor controller will be running at the extreme of its operation current and in due time may be damaged.

B: Switch channel off

In this mode the processor switches the motor channel off. It also posts an error message telling the user which channel saw an error. To start the motor again you must re-send a motor start command (or a step command). See § 14 *Appendix A: error codes.* about error messages.

C: Switch pair of channels off

In this mode the processor switches the motor channel pair off. Thus an error on channel A (or C) will also stop channel B (or D). This is most convenient for stepper motors. It also posts an error message telling the user which channel saw an error. To start the motor again you must re-send a motor start command (or a step command).

At the moment the controller will NOT automatically be into this mode if you enable the channels in stepper -motor mode. This is still open as a future enhancement. It is up to the user to set the error code for ***both*** channels into 'paired' mode.

D: Switch board off

In this mode the processor switches all four channels of the board off. It also posts an error message telling the user which channel saw an error. See the section about error messages. To start the motors again you must re-send a motor start command (or a step command).

E: Switch all motor controllers off

In this mode the processor switches all four channels of the board off. But next it asserts the HALT line. This will cause the whole system to halt: All motors will switch off. It also posts an error message telling the user which channel saw an error. All other boards will additionally post error messages telling the user that the halt line was activated. The user must re-enable all motors by sending a start command to each.

13.2 Oscillation.

If the error is "current too high" and you have set the processor to ignore that error, we get oscillating. What happens is the following:

1. When a high current is detected the controller channel is switched off.
2. This causes the current to become zero.
3. As there is no current any more, the controller channel is enabled again
4. This causes a high current to appear again and we are back at step 1.

Due to the fast switching on and off of the current some motors may produce an audio signal, a 'crackling' sound.

With stepper motors this can cause the motor to take steps and the integrity of the system is lost.

Oscillating can also happen if the error is "temperature too high". But the oscillations will be significantly slower as it takes many seconds for a device to cool down and then heat up again.

13.3 Brushed motor start/stop

Brushed motors often draw a lot of current when they start-up. This is called the inrush current. The high inrush current is likely to trip the over-current detection and stop the motor again. To prevent this from happening the Gertbot system provides a soft start or ramp mode. In this mode the signal duty-cycle starts at zero and is slowly increased till the value the user has selected.

There are no electrical issues when stopping a motor but there may be mechanical reasons where you do not want a motor to stop abruptly. Therefore the Gertbot also offers ramp-down. There are situations where you do allow the motor to stop as soon as possible. Thus the Gertbot offers a second ramp-down speed the halt-time.

When the HALT signal is activated the controller removes the power from all motor on all boards immediately. There is no ramp-down time.

There are 16 ramp values which give a range of times.

Code	Time	Code	Time	Code	Time	Code	Time
0x0	Off	0x4	0.75	0x8	1.75	0xC	3
0x1	0.10	0x5	1.00	0x9	2.00	0xD	4
0x2	0.25	0x6	1.25	0xA	2.25	0xE	5
0x3	0.50	0x7	1.50	0xB	2.50	0xF	7

Ramp time in seconds.

The value gives the time it takes for the duty-cycle to get to 100%. If the user has set the duty cycle lower the soft start will take proportionally shorter. Thus if the duty cycle is set to 50%, a ramp value of 9 will take 1 seconds to get to the desired 50% DC speed. Not 2 seconds.

Start-ramp.

The start-ramp time is used when the user gives a motor-start command.

Stop-ramp.

The stop-ramp time is used when the user gives a motor-stop command or when a change in direction is detected.

Halt-ramp.

The halt-ramp time is used when:

- The stop-all command is given.
- An end-stop is activated.

Reverse direction.

If a brushed motor sees a change of direction it will

1. Ramp-down until the power is off. It will use the Stop-ramp time for this.
2. Ramp-up again using the Start-ramp time.

Even if your brushed motor does not require soft-start to begin running, you may find that you need it to prevent extreme currents when you try to reverse the motor direction without stopping.

Beware:

The soft start sequence is only enabled when you send a motor start command. **It is not activated on each cycle of the PWM.** Thus if you set a PWM frequency of 10 Hz a DC brushed motor is started 10 times per second. You will get an inrush current ten times a second. That is likely to trip the over current protection.

Using a very low duty-cycle frequency with DC motors will cause excessive currents to flow. If at the same time the protection is set-to 'ignore errors' the controller may become hot.

14 Appendix A: error codes.

Code	Error condition
0x0000	There are no errors to report.
0x0001	Serial input queue overflow: The serial data was coming in faster than the CPU could process. One or more input bytes have been lost.
0x0002	Internal system error. System got into a state which should not be possible. This error should never appear! (Except for me when I am writing new SW)
0x0003	Mode command value error You specified a non-existing mode.
0x0004	-
0x0005	DC motor frequency error: Motor was not in DC mode. You tried to set a brushed frequency on a motor which was off or was specified as a stepper motor.
0x0006	Duty cycle error: Motor was not in DC mode. You tried to set a duty cycle frequency on a motor which was off or was specified as a stepper motor.
0x0007	Illegal frequency given in set-brushed-frequency command The frequency you specified was out of range 10Hz-30KHz
0x0008	Illegal duty cycle given in set-brushed-duty-cycle command The duty cycle you specified was out of range 0-1000
0x0009	No 'brushed' frequency set. You gave a start command to a brushed motor but the frequency was never set
0x000A	No 'stepper' frequency set. You gave a start command to a stepper motor but the frequency was never set
0x000B	Stepper motor command given to none-step channel. You gave a 'step' command to a motor which was off or in brushed mode
0x000C	Not in stepper mode You send a set-stepper-freq. command to a motor which was not in stepper mode
0x000D	-
0x000E	-
0x000F	-
0x0010	Start command given with halt active. You tried to start a motor but the halt line is active
0x0011	Attempt to set too many timer events. The program attempted to schedule a timer event but there were none left. (This error should appear during SW development only!)
0x0012	Serial output queue overflow. The board tried to send a response but the output queue was full. Data has been lost. This can only happen if you did not send enough end-of-message bytes
0x0013	Illegal frequency given in set-stepper-frequency command (0x09) The frequency you specified was out of range 1/16-5000
0x0014	Write to DAC which is disabled.
0x0015	Read from ADC which is disabled
0x0016	Enable ADC illegal mask bits. Only bits 0-3 may be set with this HW
0x0017	Enable DAC illegal mask bits. Only bits 0,1 may be set with this HW
0x0018	Brushed motor move command but channel was not in brushed mode
0x0019	Illegal command You send a command code which is not supported.
0x001A	Halt line active
0x001B	High current / hot error status seen on channel 0

Code	Error condition
0x001C	High current / hot error status seen on channel 1
0x001D	High current / hot error status seen on channel 2
0x001E	High current / hot error status seen on channel 3
0x001F	DCC message queue overflow. You send DCC messages faster than the system could dispatch them. The current DC queue can hold 256 bytes
0x0020	DCC message length error. You specified a DCC message length <2 or > 5

15 Software.

The Gertbot comes with a bundle of software. All code is available in source code and is licensed under GPLv3. All software in source code and executable can be downloaded from www.gertbot.com. The software consists of:

15.1 Gertbot Gui.

A Graphical User Interface to control the board, read the status and generate commands. The Gertbot GUI is available in source code and the project file can generate makefiles for Linux and Windows.

15.2 Gertbot C-drivers.

C-code which allows your C or C++ program to interface with the Gertbot. For a good understanding you should have a browse through this manual. A simple example for a two wheeled vehicle is available in the “srover” directory. A more complex example with per-wheel speed control is in the ‘rover’ directory.

15.3 Gertbot Python-drivers.

A python module which allows your python program to interface with the Gertbot. For a good understanding you should have a browse through this manual. A simple example for a two wheeled vehicle is available in the “prover” directory.

15.4 Gertbot DCC GUI.

A Graphical User Interface to control models trains. It is set-up to control three trains, some points and some signals.

On top of that there are several example porgrams.

16 Appendix B: Technology.

So you want to start playing with motors but you have no idea where to start. To begin with: I can't teach you all there is to know about this subject. First because I don't have the time, second because I don't know it all either even after forty five years in electronics. Fortunately the internet is a wonderful source of information, at least on the technical level where most of the information seems to be true. So read up, use search engines, use Wikipedia. What follows is just a short brief explanation of terms you might want to get familiar with

16.1 DC voltage.

A Direct-Current power source which gives out a constant voltage and current. It is often show using this symbol:



Batteries are such a source as well as most 'power bricks' which you plug between the power socket in your house and some equipment:



It seems that a DC voltage below 60V is deemed to be safe but I suggest for these motors you do NOT use anything above 18V unless you know a lot about electronics and electricity and are certain about what you are doing (Which is probably NOT the case otherwise you would have skipped this section) . Why? Read the next sections.

16.2 AC voltage.

The opposite of a DC power source is an AC (Alternate Current) which is what comes out of your home socket. AC power sources are much more dangerous than DC. An AC source below 25 volt RMS (35 V peak-peak is deemed to be safe. Anything above is dangerous).

Well you are using a DC power source of 30V so you are safe not?

NOT!


The board will take your DC power source and turn it into an AC voltage. The output of the motor controllers in stepper mode is an AC signal. The peak-peak voltage is twice the DC voltage on the input. To see how this is possible look at the section which describes the H-bridges. Thus the 30 volts of DC

you put into your motor controller will come out as 60V peak-peak AC on the stepper motor pins.
Dangerous!


16.3 H-bridge.

Below is a picture of an H-bridge. It consists of four switches with a middle tap.

The shape of which is like an H:




In reality the switches are made using transistors or FETs but for the explanation how it works switches are easiest to understand. The switches are connected to power and ground connections. So at the left we add the symbol for a battery and the complete electrical diagram becomes:




The two contacts in the middle A and B can be connected up to a DC motor.

If we close switch S1 and S3 we get that current is flowing from the + to the - following the red path in the picture below.




We see that the current is flowing through the motor from A to B. This will cause the motor to rotate.

If we close switch S2 and S4 we get that current is flowing from the + to the - following the red path in the picture below.



We see that the current is again flowing through the motor, but from B to A just the opposite direction than in the previous picture. Thus the motor will also rotate in the opposite direction.

Here are some more possibilities:



These are what is called 'braking' scenarios. The motor is shorted which means any residual current in there can flow and will cause the motor to brake. The Gertbot does not support these two modes.


There are two more possibilities but those are never used: If S1 and S2 are closed or if S4 and S3 are closed. In that case the switches form a short circuit from + to - and unless precautions are taken something will get damaged.

Note that the original DC voltage of the battery is now changed into an AC voltage on the motor. Contacts A and B have a voltage swing which is twice the battery voltage. As AC voltages are a lot more dangerous than DC you should not use voltages above 18V unless you really, really know what you are doing.

16.4 DC Brushed motor.

DC motor, brushed motor or DC brushed motor are all names of a motor which runs of a DC voltage. The more voltage you apply the faster it runs. The force it can apply also goes up with the voltage. Unfortunately this means the running a DC motor slowly and still providing a lot of force is not possible.

A DC motor has a single coil:




You can reverse the direction of rotation by reversing the voltage over the wires or by swapping the wires around (which is the same).


16.5 Stepper motor.

16.5.1 Connections

Most stepper motor come with four or six wires. The following is a diagram of a stepper motor with six wires:




To generate a magnetic field you have to send a current through one of the coils. There are several ways of doing this. Here we connect the middle of a coil to the + and then we can use two switches to enable either one or the other coil.




The blue arrow indicate the direction of the magnetic field. As you can see the two operating modes have opposite magnetic fields. I have not drawn it, but you can imagine that the same is possible with the coil at the bottom. The advantage of this method is that you need only two switches to flip the magnetic field of the coil around. But the disadvantage is that you use only half of each coil. For two sets of coils you need four switches.

In the following diagram we drive the coils from their extreme connections. The middle tap of the coil is not connected to anything. Again we get two opposite magnetic fields but in this case the full coil is active so the magnetic field we can generate is twice as strong. But to drive the connections from **A+**, **B-**

to the inverse: **A-**, **B+** you need more than two switches. If you have read the previous paragraphs it will be obvious that this can be achieved with an H-bridge. For two sets of coils you need two H-bridges.




A stepper motor with four wires is not much different from one with six wires. The middle taps of the coils are missing:



16.5.2 Mechanics

Most stepper motors have a permanent magnet with 'teeth' which is mounted on the axis. The following are a set of diagrams which try to explain the principle of operation. The current in the external coils is changed such that the rotor is moving from one position to the next.



In reality the internal of the motor is much more refined, with many small teeth and two sets of teeth on the rotor. The two sets of teeth are slightly offset and the magnetics are controlled in such a way that the rotor switches from one set of teeth to the other.

16.5.3 Rotor hold.

From the pictures in the diagram above you can see that the rotor will be held in place if the magnets are active. However if the power is removed from the magnets the rotor can freely turn. This means a stepper motor that is halted (not running) can be stopped in two different states:

- Stopped with magnets off.
In that case a small external force can change the position of the rotor.
- Stopped with magnets on.
In that case the rotor will stay in position and it will take great force to move it out of position.



16.6 Inductors.

The windings of your brushed motor or your stepper motor are inductors. You should know a bit about inductors if you want to work with motors.

16.6.1 Switching it on.

First rule of inductors: They don't like a change in current!

So they will 'fight' any increase in current. The following might sound strange but: as soon as you put a voltage on the coil there will be at the beginning no current! No current means no magnetic field and thus your motor will not make any movement. After a while (a few microseconds to milliseconds) the current will start flowing and slowly the magnetic field will increase and the rotor starts moving. The following is a diagram plus graph, showing what happens if you apply a voltage to a coil:



At time $t=0$ we close the switch. The current starts to rise and after a while it gets to its maximum value. The time that takes depends on the motor coil. In a small coil it can happen in a few microseconds, a large coil can take several milliseconds to reach the maximum current.

In the diagram you will notice a resistor next to the inductor. That resistor represents the internal resistance of the inductor. The resistance is important as it determines the final current value which will flow. A good inductor will have a very low resistance.

Beware that this effect is totally different from the in-rush current. The in-rush current is caused by a lack of counter-magnetic field when the rotor is not yet spinning. The in-rush current also happens on a different time scale: in tens of seconds to seconds, not the micro- and milliseconds mentioned above.


16.6.2 Switching it off.

First rule of inductors: They don't like a change in current!

This also means that if there is already a current flowing and you try to stop that the inductor will fight that as well. One way to fight the current is that the inductor will 'push back' by generating a counter-voltage. This is where inductors can get very, very nasty. If you switch the current off, the 'push back' voltage of the inductor can become thousands of volts high⁸. First it can give you a nasty shock (literally!). Second it can blow up your circuit. To prevent this the motor controllers have built-in protection diodes.


16.7 Quadrature encoders.

Quadrature encoders are sensor on a mechanical system which tell you in what direction the system is moving. It consists of two sensor which each produce an electrical signal. The waveform of a quadrature encoders is a Gray coded signal:



The signals change in a known sequence: 00, 01, 11, 10, 00

If the mechanical system moves in the opposite direction the sequence reverses:



The signals now change in a sequence: 00, 10, 11, 01, 00

If we add a counter to the system we can keep track of the position. Each step in one direction we increment the counter, in the opposite direction we decrement the counter. By measuring how fast the signal changes we can also get an indication of the speed at which the mechanical system moves.

⁸ That is how the ignition spark in your petrol engine is generated!